Certificate of Location of Government Corner

ID#: 852809 **Description:** SEC CEN 28 85 **Date Set:** 5/24/2004 **County:** Olmsted

Section: 28 **Township:** 108N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" pipe w/cap RLS #14888

Reference Ties:

The monument is down 0.1'
The corner falls 2' east of N-S fence and 2' south of 30" Oak
This corner is located by GPS reference stations "Mensing I & II"

Corner History:

5-13-1863 P.C. Compton (P.70 No.99 S) set stone with glass and cinders, written on plat as placed etc.

7-1910 Ch. Larson (P.130B) used corner post for survey. Claimed in mound. Meas south 39.95 2636.7'. 16 south set point for line west, no disc of 1/4 28-33.

10-1971 County Surveyor walked to corner area with farmer Bruce on squirrel hunt. Probed entire area of N-S-E fences, found nothing positive as area of fence east could be any where. Maybe aerial from N & S 1/4 corners as now set may help but neither likely same as Compton corner. Ch. Larson corner data of no value. Corner could be there if not in open fields W and SE. Found iron shaft west claimed by farmer as set by surveyor likely Ch. Armstrong. No W 1/4 corner known of sec 28.

4-24-2000 County Surveyor found fences N-S-E.

5-24-2004 V. Fangman set 1/2" pipe w/cap #14888 at intersecting quarter lines.

1-25-2006 County Surveyor found 1/2" pipe w/cap RLS #14888 at surface in good condition.

3-19-2012 County survey crew found 1/2" pipe with cap RLS 14888 in good condition.