Certificate of Location of Government Corner

ID#: 933104 **Description:** S 1/4 SEC COR 31 93 **Date Set:** 7/1/1977 **County:** Wabasha

Section: 31 **Township:** 109N **Range:** 13W **Monument Description:** 1/2" pipe

Reference Ties:

The corner falls 2 1/2' east of centerline of Wabasha CR 11
This corner is located by GPS measurement

Corner History:

9-27-1853 Gov't Notes: Elisha Norris, Deputy Surveyor; west corrected on south side section 31. 40.0 chs set quarter section post in mound with trench, pitts, and cherry stones planted N & S.

7-1977 Olmsted County Surveyor found pipe by T. Taylor. Dug from pipe South 7', West 2', East 2' and North 1'. Found nothing reset pipe at surface.

4-26-1995 Olmsted County Surveyor found pk nail at surface of CR 11 and 1/2" pipe 7" deep.

11-15-1995 David Johnson, Wabasha County Surveyor, found 5/8" pipe and removed. Dug a 10' square hole down to subsoil and fond nothing. Set 1" x 18" pipe at the 5/8" pipe location and accepted as corner.

7-16-2007 Olmsted County survey crew found 1/2" pipe without cap down 0.8' in good condition.