Certificate of Location of Government Corner

ID#: 933504 **Description:** S 1/4 SEC COR 35 93 **Date Set:** 5/17/1976 **County:** Wabasha

Section: 35 **Township:** 109N **Range:** 13W **Monument Description:** 1 1/4" pipe

Reference Ties:

The monument is down 0.4'
The corner falls 5' north of centerline of E-W twp road and 10' east of centerline of driveway north
County Survey Disk in PP #32475 ENE 169.48'
Steel post (at T) in concrete at NE corner of quonset SE 178.27'
Steel post (at T) in concrete at NW corner of quonset SE 157.65'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Elisha Norris, Deputy Surveyor; West corrected on south side of section 35. 40.0 chs set quarter
Section post in mound with charred stake, trench, pits, and cherry stones planted north and south.

5-12-1976 Olmsted County Surveyor dug and found no evidence of corner.

5-14-1976 Olmsted County Surveyor found a 4"x4" / 10"x15" sandstone lying flat. Found black mark beneath the stone extending. 6" into clean clay. Found wood pieces beneath stone that may be remains of a stake. Accepted stone as corner and reset it over the mark and put scrap metal around the stone.

5-17-1976 Olmsted County Surveyor set a 1 1/4"x2' pipe over the stone found 5-14-1976.

9-20-1979 Olmsted County Surveyor found the pipe set 5-17-1976.

3-12-2007 Olmsted County survey crew found 1 1/4" pipe bent west. Dug out monument and staightened, reset in same hole below bend. Fence post w/CSD gone as well as CMP, quonset gone but foundation still there, did not look for ties. PP w/CSD has been replaced.

7-5-2007 Olmsted County survey crew found 1 1/4" pipe down 0.4' in good condition and measured using GPS.

7-11-2012 Olmsted County survey crew found 1 1/4" pipe in good condition.