Certificate of Location of Government Corner

ID#: 933605 **Description:** S SEC COR 35 36 93 **Date Set:** 8/8/2007 **County:** Wabasha

Section: 36 **Township:** 109N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface
The corner falls 1/2' north of centerline of CSAH 11 and 3' west of centerline of twp road north
County Survey Disk in W side PP #32416 NE 71.77'
County Survey Disk in SW side PP #32400 SE 54.39'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Elisha Norris, Deputy Surveyor; West corrected on south side of section 36. 80.0 chs. Set post in mound with charred stake, trench, pits, and cherry stones planted at each angle for corner to sections 35 & 36.

5-14-1976 Olmsted County Surveyor found a 7"x9" topped sandstone 18" long and 5' deep. Set scrap metal around stone and set a 1 3/4"x3' pipe over stone. RPs- nail in lath on pp NE 71.23, chisel T in SW headwall NNW 175.2, chisel T in E headwall NNE 181.0, corner 3' west centerline road N and in cneterline E-W road.

9-20-1979 Olmsted County Surveyor set a 1" square by 35" pipe with cap from 1976 references. RPs-
Chiseled "T" in south end concrete headwall NNE 181.0, CSD disc west side pp #32416 NE 71.71
Punch hole top center west end CMP in field drive north NE 62.77, CSD disc SW side pp #32400 SE 41.66, Chiseled "T" in SW corner concrete headwall NNW 175.2, Pipe is 1/2' north of centerlin E-W road and 3' west centerline road north.

3-12-2007 Olmsted County Surveyor found 1" pipe with no cap down 0.3'. Set new cap.

7-3-2007 Olmsted County Surveyor found 1" square pipe w/cap down 0.3' in good condition and reference for 2007 overlays.

7-7-2007 Olmsted County Surveyor removed 1" square pipe w/cap for overlay.

8-8-2007 Olmsted County Surveyor set 1" square pipe w/cap at surface from 2007 overlay tie-out.

12-2-2011 County survey crew found 1" square pipe with cap in good condition.