Certificate of Location of Government Corner

ID#: 953205 **Description:** S SEC COR 31 32 95 **Date Set:** 11/16/2001 **County:** Goodhue

Section: 32 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls 1' north of centerline of 8th St SW and 12' west of centerline 3rd Ave SW north
1/2" rebar NW 45.34'
SW corner house foundation NW 149.5'
County highway disk in PP SW 99.0'
County highway disk in PP SE 69.45'
40d spike in CP NE 50.7'
This corner is located by GPS measurement

Corner History:

9-1853 Elisha S. Norris, Deputy Surveyor, set a section post for the corner during the original Public Land Survey.

7-1909 J.M. Simmons, Goodhue County Surveyor, shows a stone at the section corner for a survey of the west line of Section 32.

1939 J. Kerr's Pine Island Bk.1Pg.6: RPs to SW corner section 32- E 228' to 60p in 36" elm, SE 162.75 to NW corner Tile barn.

1966 J. Kerr took additional ties. WSW to nail and disc in transformer pole 99.0', NW to SW corner house 149.50', NE to 60d spike in fence corner post 50.7', SE to nail and disc in PP 68.50'.

(NOTE: I replaced this corner because it is a control over the north line of Olmsted County, this being on the correct line.)

7-1981 Doug Rude, Crew Chief for Yaggy Associates, Inc., found the described cast iron monument, which checked the remaining ties. New land ties were recored. The monument is accepted as marking the Public Land Survey corner.

? 1/16 corner east concrete monument with iron cap (Pg.33 - 286.72' east to iron monu.) RPs- (Pg.9 Bk.1) NE spike in root of 33" soft maple 15.0', SE spike in 18" soft maple 28.0' (near bottom). Pg. 25 gives measure west 1913.75' to iron.

3-19-2001 Olmsted County Surveyor found CIM down 1.3' in good condition and located its position with GPS.

11-16-2001 Goodhue County Surveyor set telspar monument over CIM.

1-5-2006 Olmsted County Surveyor found cast iron cap on telspar pipe at surface in good condition.

3-15-2012 County survey crew found cast iron cap in good condition.