Certificate of Location of Government Corner

ID#: 953304 **Description:** S 1/4 SEC COR 33 95 **Date Set:** 8/21/2003 **County:** Goodhue

Section: 33 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The corner falls in centerline of 8th St SE
This corner is located by GPS reference stations "Green View A & B"

Corner History:

9-9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West on corrected south side of section 33. 40.0 chs. set quarter section post in mound with charred stake, trench, pits and cherry stones planted north and south. Could find no other records.

11-2-1981 Olmsted County Surveyor dug with backhoe at Gov't corner location as set up by a private surveyor doing a survey in section 33 T109N R15W. Diggings came 4' south, 5'east, 6' west, and 7 1/2' north of Gov't distance from field break east. Found remains of a small post 1' west of this point. Found nothing further. Diggings 2 1/2' deep under fence.

11-17-1981 Olmsted County Surveyor set a CIC on a square pipe at location of small post found.

10-14-2002 Olmsted County Surveyor found Pk Nail at surface in good condition.

8-21-2003 Goodhue County Surveyor set telspar monument.

1-27-2006 Olmsted County Surveyor found CIC on telspar pipe in good condition at surface.

3-15-2012 Olmsted County survey crew found cast iron cap in good condition