Certificate of Location of Government Corner

ID#: 953305 **Description:** S SEC COR 32 33 95 **Date Set:** 8/21/2003 **County:** Goodhue

Section: 33 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls in centerline of 8th St SE
NW corner of catch basin NE 47.04'
Top hole at end metal grate SE 50.18'
This corner is located by GPS reference stations "WZ A & B"

Corner History:

9-9-1853 Gov't Notes Surveyor Elisha S. Norris; 80.0 set post in mound with charred stake, trench, pits, and planted cherry stones at each angle.

11-6-1981 Olmsted County Surveyor dug for corner and found nothing.

11-17-1981 Olmsted County Surveyor set CIC w/ square pipe. Between the S 1/4 corner 32 and the S 1/4 corner 33.

10-14-2002 Olmsted County Surveyor found pk nail at surface in good condition.

8-21-2003 Goodhue County Surveyor set cast iron cap on telspar pipe.

1-27-2006 Olmsted County Surveyor found CIC on telspar pipe at surface in good condition.

3-15-2012 Olmsted County survey crew found cast iron cap in good condition.