Certificate of Location of Government Corner

ID#: 953505 **Description:** S SEC COR 34 35 95 **Date Set:** 1/8/2013 **County:** Goodhue

Section: 35 **Township:** 109N **Range:** 15W **Monument Description:** 1" Brass Plug with Punch Mark

Reference Ties:

The corner falls in centerline of twp road north and 5' north of centerline of E-W twp road and 0.9' NNE of north edge of sanitary sewer manhole.
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West corrected on the south side of section 32. 40.0 chs. Set quarter section post. RPs- 7" jack oak N70°W 83 links, 6" jack oak N55°W 64 links

Could find no other records for this corner.

5-1975 Olmsted County Surveyor found large boulder 12"x16"x21". Boulder falls in centerline road north and 7' north centerline E-W road. Set 1" pipe at surface.

11-9-1996 Goodhue County Surveyor set telspar monument over 1" pipe.

7-6-2001 Olmsted County Survey Crew found 1" pipe in good condition.

5-10-2010 Olmsted County Survey Crew visited area, searched by coordinates and did not find anything. The monument appears to have been destroyed by the recent construction of a sanitary sewer manhole.

1-8-2013 Olmsted County survey crew set a 1' brass plug with punch mark at the location of the previously measured 1" pipe. The brass plug is 0.9' NNE of the north edge of a sanitary sewer manhole.