Certificate of Location of Government Corner

ID#: 953605 **Description:** S SEC COR 35 36 95 **Date Set:** 11/5/1996 **County:** Goodhue

Section: 36 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of E-W twp road and in line with pasture fence north
Chisled "X" NE corner concrete box culvert WNW 103.03'
Chisled "X" SE corner concrete box culvert WSW 103.38'
This corner is located by GPS measurement

Corner History:

9-1853 E.S. Norris, U.S. Deputy Surveyor, set post in mound with trench and pits.

5-1868 H.G. Clark, Pine Island Town Clerk, filed a Plat of Survey for a road to run east on the County line from the South Quarter Corner Section 35 and intersect with the St. Paul and Elliota road.

9-1996 Dennis L. Robinson, Goodhue County Deputy Surveyor, supervised the excavation for the corner at intersection of east-west road and fence line north. An area 10-feet by 14-feet by 5-feet, 10-inches deep was searched. Old road be found at depth of 3 feet, 5 inches. No evidence of monument was found. The area under the old roadbed appeared to have been disturbed. Also excavated 7-feet by 12-feet by 6-feet deep to the east of first excavation to cover lost location, nothing was found. An analysis of the record and field evidence indicates the east-west County line road was surveyed in 1868 to run on the line, and it was also determined to fence line along the east line of the Southwest Quarter of the Southwest Quarter would agree with the fence line along the west line of the Southwest Quarter.

11-5-1996 Goodhue County monument was set at the intersection of east-west road and fence line north. This position is accepted as the best evidence of the Location of the Original Public Land Survey corner.

7-7-2001 Olmsted County Surveyor found CIM in good condtion down 0.5'.