#510409

1

1/4 corner Center 4 Elmira 105-11.

10-1897 H Fraser P612 No 556 & 4 H.M. Coulson

drove stake well down with stone by side at true intersections

1/16 south - set limestone with boulder on either side

M & L 19.77 (1304, 8 S 10' E & S 89 3/4° W.

6-17-76 dug in area of corner post. Found base of old post about 1' E of corner post. Did not look further.

6-24-76 ~~Dug~~ doubled line and measure from S 1/4 Sec 4 (found) over 1/16 N (found). Point came at location of old post. Dug down to clay 3'x3' on SE side new corner post. Found it

6-24-76 Measured N from S 1/4 Cor 4. Found limestone between two boulders 4' N of the corner post and under N-S fence (at ~~1304.56~~ 1304.255).

Inv. From Coord