7-13-76 CIM

#510506

1

1/4 corner 5-6 Elmira 10 5-11.

5-1875 Hunter P 278 No 275 26 J Halloran.
found mound with part of old stake in center, set stone
boulder 8 x 10 x 18 BT & grubbed out
Meas west to center stake 40.01 N 89 3/4° E

Gen'l Note 8-1853
Set 1/4 post as 1/4 cor.
10" Burr Oak N. 19° E 454 Lks. (299.64)

7-13-76 Dug with backhoe and found stone (as recorded by Hunter) on the East side of the Twp. Road. Found the top corner broken off. Covered the bottom portion of the stone and drove a 1/2" rod on the W side and a flat iron on the E. side. Also

placed an old wrench beside the stone. Set a CIM over the stone and filled the hole. Corner is approx .10' W of Line and 2637.0' N of Sec. Cor. 56-7-8.

Ref. CSD in corner post W 32.05

CSD in pp# 2065 SW 120.25

Spike & Disc in S. side of Soft Maple Cluster E 23.13

Corner fall 6.0' E of ℄ N-S. road and in line with fence W.

7-8-96 1/4 COR 5-6 ELMIRA 105-11 Fd CIM in good shape 4" deep in crushed Rock 150th Ave SE.