/

#511009

1/4 Corner Center 10 Elmira 10 5-11
4-1892 Thos Fraser. P 477 No 456 & 10-11 2 Trees Fairish.
set 3 stones with center stone as corner,
a wedge shaped stone, all 3 about 18" long.
New B Tree & 1° W 8" burr oak - 14 1/2 lks 9.6'
1/16 south set small stake M & L - as set was 2 5/16 lks
too far south but did not adjact Corner as ditch use.
1/16 east set stone 3 x 6 x 20, glass below, M & L 19.95 13/16.
1317.22

8-11-1975 Co. Surv. - Found several stones
standing - N.W. side of Cor. Fe post - Fences E-W-S
used Point Between 2 Pointed Limestones Over

1

New RP's – C. Surv. Disc. in – E. side – 12" Burr oak – S.S.W. — 59.0
Co. Surv. Disc. in N.W. side – 12" Burr oak – W.S.W — 17.6

Set 1" x 39" drill steel shaft

1/16 E 8-11-75 Dug around base of corner post and 2' ft East to cover Fraser's full measure but but Found only 3" x 8" x (20"?) limestone lying Flat on N. side of corner post (no glass)

8-29-75 Center SE 1/4 Sec 10 Dug and found possible stone 7" x 9" x 16" broken and lying flat in S. road ditch. Black soil deep – could find no mark. did find piece of glass. Set iron piece around.