1 · 6-28-76 Set Rock #511704 #1

12-20-82 set 5" sq. w Cap on Concrete

¼ corner 17-20 Elmira 105-11

6-1899 Pl Frazer P656 No 585 L17-20 Town Board.

corner gone, no evidence or knowledge so set.

stone 3 x 14 x 24 40.07½ M & L. N 89° 40' E

1935 Co H D B 75 P 76 assumed cor.

Sp in 18" Maple L E 53.8' - Sp in F P S W 49.8.

15" brook N E 83.5 - Sp in P P N W 40.9

1964 Co H D B 295 P 10 assumed corner, set drag Lath

not clearly described or developed

Sp D P P W 34.78. Sp cor P N E 70.55

Sp D Brace P E S E 40.79

Meas. south to Accum Center 20. 2650.86 1 over

Corner set in line fence west

Gov't notes: set gr. sec. post and stone (no size)

6-21-76 Dug with backhoe 2' deep to clay at W.F. measure from Sec. Cor 17-18-19-20 (found) and W.F. measure from E-W fence at center 17. Dug $\frac{7}{5}$ in center of S bound lane (Co. Rd 30. digging from 5' S of fence W to 2' N of fence W. Found nothing.

6-28-76 Dug and found W.F. stone 5.05 S. and .45 W of trashee nail and 1½' deep, Corner 5' South of fence W, 18' S. of ℄ rd E. Set ½" x 12" rod.

R.P.s: Disc in P.P. West 34.5 gone 5-1982
CSD in P.P. Brace ESE 72.69
20" Twin maple (Disc N. side) ESE 171.54 too far

¼ Corner 17-20 Elmira 105-11 #511704 #2

8-8-77 Tied corner for road grading. Corner 4' So. of fence W.

RP's ½" x 2' rod (cup 4" with hub on So side) 3' So of fence West and on line to P.K. in power pole 400' ± West West 139.27

5-14-1977, ¼ Cor 17-20: Found ⅝" rod (appx) at road surface after road graded. Possibly C.H.D. Found the ½" rod set 139.27 West (looked OK) 8-8-1977 but the hub was plowed out. Projected line and measure from P.K. in power pole over said iron and point came .09 West and .14 South of iron found. The CSD in power pole ESE 72.69 Taken 6-28-1976 is still in place, so we used this shorter distance for E-W control and the line from West (P.K. over ½" rod) for N-S control and set a concrete nail which caused .05W

and .14 South of the C.H.D. mon.

5-25-82, 1/4 Cor 17-20: Pulled CHD mon and set it at location of concrete nail set 5-14-1982. Corner 4' South of fence West and appx 19' So. ℄ rd E, and in Center N-S rd.

RP's: Plastic Disc in N. side power pole WSW 61.39
Punch mark in lug at top N. end CMP NE 53.01

12-20-82
Set 5"x1" Square with cap in Concrete 0.08' East of ℄. Took No addl R.P.'s
Set up corner as on 5-14-1977 and checked OK against RP's.