1/4 Cor. 26-35 Elmira 105-11
6189 FD STONE SET C.I.C. 1" P² IN PLACE
Gov't notes: Set post and Limerock 18"x12"x2"
Mound and pits #512604


Corner of 3 farms - common land on east side
govt notes say land at corner level
Contours drop sharply to south into bottom lands

5/12/89 VISITED APPROX. CORNER LOCATION FENCES N-S-W, ROCKY AREA

6/27/89 DUG @ C.P. TO FENCE N-S-W WHOLE AREA WAS FULL OF FLAT ROCKS JUST BELOW SURFACE OF GROUND DUG FROM T.N. ON SOUTH SIDE OF C.P. NORTH 4' E & W 2' FD NOTHING HERE. WE DUG ON So. SIDE C.P. AND FD A STONE 2"x 12" x18" WHICH MATCHES GOV'T STONE SIZE, THE STONE WAS LEANING NORTH

Cont. ↗

Cont.
THE STONE WAS SET WITH POINT DOWN. THIS WAS THE ONLY POINT WHERE THERE WAS A BREAK IN THE ROCKS COULD FIND NO WOOD. THE STONE IS APPROX 2' SO. & 1' WEST OF T.N.



6/30/89 SET C.I.C./P² AT STONE LOCATION, WITH STONE DUG IN 1/2' SO. RP's
C.S.D. IN C.P. NNE 2.43'
SPIKE & C.S.D. IN 16" ELM SO. 16.48'
CORNER IS 2' SO. OF FENCE WEST & 1' WEST OF FENCE SO. NAILED SURVEY SIGN TO C.P.