/

#523405 (1)

Section Corner south 33-34 Orion 105-12.
2-1904 C armstrong P 72 B S 33-34 See 1/4 34-35.
ground froze. didn't find corner. Set temp point
for line. 60 links east of (iron stake CA did not find set by Murphy)
Fillmore surveyor ac. section corner.

Gov. Notes 1853 Sept.
West on south boundary of section 34.
80.00 Set post for corner to section 33 and 34.
Aspen 16 in. ~~N50W 29 lks.~~ N2E 37 lks.
Blk Oak 10 in. N50W 29 lks.

8-13-1979 We dug with the backhoe centered over a point
30 links East of Case's iron at N 1/4 Cor 3. We found
a 1" diameter rusty black hole extending deep into

clay beneath old road 4' deep which is probably where the iron found 8-7-1979 stood. This mark was 19.8 East of Cast iron and we drove a RR spike in it to retain its location. It is 1' So. E-W ℄ and 1' E fence line North. We also found an 8" square mark filled with wood piece in the clay beneath the old road We drove a 1½" pipe in the center of this mark and drove a 2"x2" hub in the top of the pipe. This mark is ℄ E-W road and 2' W fence North. See Drwg. for Coordinates. Sq Mark } WSW 7.2 NNE 7.97 Iron Mark } N 8.55 W 9.65

8-30-1979 Set a CIM ~~at the location of~~ over the pipe set 8-13-79 in the sq. mark with woodpiece.

RPs: Disc in power pole #43020 SSE 42.58
CSD in corner post SW 55.67
CSD in corner post North 41.63

North 1/4 Corner Section 3 Jordan Twp. 104-12 (2)
#523405
File with S. 33-34 Orion Twp

8-7-1979 We dipped a 1" x 30" shaft lying flat about 3' deep in the center line of the road south and about 3' N ℄ E-W road. We will dig visit later - may find the mark where it stood.

8-13-1979 dug with the backhoe to cover the ℄ of the road South and also midway between the fence South at N 3-4 and the fence N. and N 2-3. Found Case 1½" x 2½" x 30" iron lying flat 4' deep beneath old road. We easily found the mark where it had stood and drove it down through the mark. It came 4' West ℄ rd South and 1' South ℄ E-W

road. Set spike at road surface. LRP { SW 8.38 / SE 9.12

9-30-1979 Set 5/8" iron in place of spike set 8-13-79

RP's: CSD in pp #43020 SE 48.53 See Blue Book for history on N1/4 Cor

CSD in corner post NNE 47.13

CSD in corner post SSW 47.19

Tie to Olm Co. S. 33-34 in East 1/4 17.3 at S. 33-34 Cor

1/16th East: 8-14-79 Dug small hole in ℄ E-W road and in line with the fence So. Conditions poor with clay 1½' deep beneath the old road but improve if the point would fall South of ℄.

8-16-79 Dug to cover N&L from Case's corner found at the N1/4 3 to a point 15' North of the T.N. at N2-3. This point came on the South shoulder of the E-W road and in line with the fence South across ditch. We found nothing and conditions are very poor with only a trace of black sand or clay.