7-26-1979 CIM

1/4 Corner 28-29 Pleasant Grove (1)

#532804

5-21-1979 Dug in the center of the E-W road and in line with the fence South. The surface of the road was in 1' to 2' cut on the North side and 2' to 3' cut on the South side. We dug 1½' deep but found only fill or clay. Dug from 2' North to 3' South of ℄ and 3' West to 5' East of the fence line South.

1/16th East 6-21-1979 Dug and found a 6"x10"x18" stone with drag tooth on the North side. Set a ½"x18" bolt on the South side. The corner is ±5' South of ℄ E-W road and is 2.35 South and .3 East of the tree nail.

LRP W 4.67 N 3.43

LAPS to Tie Nos. 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12

6-21-1979 (¼ Cor 28-29) Dug with the backhoe at double the line and measure of the corner post at the 1/16th South. Dug from this point West to cover total line from SW 28 to NW 28 Found nothing

7-26-1979 Set a CIM over a ~~½"x18" rod at the location of the stake found 7-23-79~~ ½"x2' rod on line from the E ¼ Cor 28 (as set this survey) over the stone found at the 1/16th East (of ¼ Cor 28-29) and at double the measure from the N-S ¼ line Sec. 28 over the 1/16th stone. The corner is in line with the fence South and 5' So ℄

RPS C.S.D. in SW side pp# 14858 NW 84.49
CSD in E side c.p. South 24.08

quarter corner 28-29 Pleasant Grove #532806 1 2

Corner Notes

No. on Sec quarter section post

B- Oak 7 N75 E29

Black Oak 7 N26 W 415