1/4 Corner Center 28 Pleasant Grove
#532809

6-1979 dug from a point 14' West and 2' S. of the traverse nail West for 5' and South for 8'+ to clay. Found nothing
(Traverse nail on E shoulder of road and 6' North of rd. West)