X 6-25-81 Set CIM #533205 (1)

Section Corner south 31-32. Pleas Grove 105-13.

5-1893 H Fraser P528 No 493 S 31-32-33, E North, C w/Bates & Bruster.
SEE also Pg 530 No 494

set stone 4 x 12 x 24. on line S 1/4 sec 33 and prop
mean of 40.01 1/4.

— 1/16 north set stone 3 x 15 x 18 M & L 19.97 in road.

4-1942 J Kerr B27 P4

found & used stone. (possibly - may have found only 1/16 N)
- mean east to stone found 2639.8.

— 1/16 north found stone at 1318.05' 5 x 8 x 18

4-24-1981 RWB & Dave Knutson (Fillmore Co Surveyor)
found L.S. with 2"x6" Top - bottom of stone
much larger, but did not dig up except Top
part (±14") Corner lies under E-W fence and
± 10' E. of Corner of fences S. & E.
Also ℄ N-S Road on Curve is ±95' West.
Located this L.S. by Knutson's Traverse of 1st
Standard Parallel using W. Fraser's line & meas.
which fit the appx. location within 1 foot.

6-25-1981, S. Sec Cor 31-32: Fd. stone that Dave Knutson found. Removed stone and set CIM over ½" iron with W. Fraser stone on South side. Put Post & Sign 1.2 N. of CIM.

RP's: CS Disc & spike in 14" pine NNW 28.89
Spike & C.S. Disc in 16" pine West 21.37
CIM under E-W fence and ± 10' East of fence South.

Section Corner South 31-32 Pleas. Grove 105-13
#533205 (2)

8-20-82, 1/16 North: Dug with backhoe from t.n. set in 19—. First found a 3"x11"x17" shattered limestone (3 pieces) dug in and standing. Top down 20". (This stone 1.3 So. of Will Fraser's stone Fd. next). Dug further and found Will's recorded stone standing just North of the shattered stone and 2.45 East and .1 North of the t.n. and 18" deep. Put scrap iron around stone. Also Fd a 1"x2" pub just below the road surface and .3E. and .2 N. of the center of Will stone.

t.n. { E 8.80 / S 7.80 hub { E 6.15 / SSW 8.40 Will's stone { E 4.45 / SSW 8.20 1st stone { ENE 6.70 / SSW 6.65

File with S 31-32 P.C Section 5 Sumner Twp 104-13 (3)

#533205

See W.F. Survey No 494, Page 530, Book A

Center 5 5-5-81 : Dug for Fillmore Co Surveyor in line with fence West and on West 1/2 of N-S road. Did not find Will Fraser's 22x10x2 stone. We did find a pointed boulder 10 x 14x17 dug well down into clay with smaller boulder packed around about 3' deep. The Fillmore Co. Surveyor tied this stone into his Section 5 traverse.

1/16 N. of Center 5 5-5-1981 : Dug on West shoulder of N-S road. Found 13x14 rectangular mark in clay with small piece of limestone about 3' deep. Found nothing further. The Fillmore Co. Surveyor tied this point into his Sec. 5 traverse.

1/4 Cor 5-8 5-5-01 : Dug centered appx 1' West of fence South and in the center of the E-W road. Dug 4'+ to clay but found nothing

(2621.29)

N 1/4 Cor 5 Fillmore Co. Surveyor set CIM midway between NW 5 and NE 5 and on line SW 31 to SE 31 (S 1/4 31 set at calc. (2632.31) M & L) See Cut in Blue Book @ S 31-32

Corner 27' West of centerline of rock road and 3.5' South of fence running West

Nail with blue plastic in NW Face of pp WSW 9.69

Nail with blue plastic in SW Face of 3rd pine North of Fence NW 39.48