South 1/4 Cor. Sec. 36 Pleasant Grove 105-13
#533604

Government Survey tie of 2.86 Chains (188.76) West to Fillmore County Corner (a mound)

6-3-91 NE 1, 104-13 : Dug with backhoe & Fd. 2" square Iron with 6" square plate with raised lettering, set a 1" square pipe at surface. Corner is in ℄ of road immediately South & 6' No. of ℄ E-W road. Chained 193.86 East to Trav. Nail at So. 1/4 36, 105-13. Iron 4.8 deep

R.P.s: Chisel Cross in N. end 60" Culvert ENE 38.91
Chisel Cross S. End 60" Culvert SE 57.01
Chisel Cross W. end 60" culvert SW 69.54

LRP E 9.15
SE 14.00

6-4-81 S. ¼ Cor. 36: Dug with backhoe at Cont'tie of 188.76 East of NE 1, 104-13. 7d. nothing. Poor conditions.
Dug 2' East, 5' South, 9' West, & 3' No. of Trav. Nail. by 5' deep.
TRAV Nail { SW 12.96 / SE 13.02

6-5-81 ¼ Cor 35-36: Dug from t.n. East 3', North 4', West 6, and South 5' of the traverse point. Found nothing. Poor Condition. Drive in clay

9-9-82, S ¼ Cor 36: Set a CIM over a ¾" x 15" iron on line from the S. Sec. Cor 35-36 (reset this survey) on the NE Cor Sec 1, 104-13' ~~[illegible]~~, Fillmore County and at 188.76' (Cont meas.) from the NE Cor Sec. 1. The corner falls 7' North of the ℄ of E-W road.
RPs: CSD in pp # 13375 NNE 36.37
Punch mark in N. end 60" CMP ENE 50.36