#540109

1/4 corner center 1 Hi Forest 105-14.

11-1907 Ch Armstrong P110 B J Kelly, R Thomas & others set 2 boulder stones one above the other inters lines -16 south set stick of oak stone wood & 3 chimney bricks. M&L. 1970 (1300. 21.

-16 west. set stone ~~7½ x 18 x 26~~ on plat M&L no mens. or temp post

-16 center of W 1/4 Sec 1 set limestone 2x8x20 M&L 19.95 on E-W 1/16 line of W 1/4 1.

late unidentified survey - boulder west side of corner fence post in fence running north & south

(over)

7-3-1974 Co. Surv.

found Apparent bottom boulder (5"x7"x12") with old rotted post stub on E. side of stone, Top of Stone down ± 1' Set stone upright (it was leaning slightly To North) and placed 3/8" steel fence post on N. side with Top of post over center of stone. Corner falls under N-S fence but in old crossover lane and nearly in line of Main fences E & W.

Place between 1/4 1-2 & 1-2-11-12

16th corners on east & south sides of SE 1/4 section 2 Hi Forest 105-14.

—16 north stone 1½ x 18 x 26 set by armstrong P. 110 B set M & L 19.44. 1283.04 or 2566.08 1907.

present day corner a pipe. M & L 1284.77 or 2569.54
Sp tele pole NW 36.0 - Sp power pole SE 52.3
Sp " " NE 62.6

over.

—16 corner east of Center 2 - ½" rod. set by Sankstone some 10'± north of E-W fence. When McGhie run same line set corner within hundredths on prial of line. no ties, no N-S fences in pasture.

1/16 corner. west of SE cor 2.
pipe 1½" x 30" set by armstrong 11-1907 P110 B.
at 20.05 M & L.
corner found and used in early 1950's 1338.0
west of SE 2. corner now gone in backslope new grade.
RPs recent- Dec 15" oak S.W. 84.8 ✓ ← cor tree (we think)
120 D 4" burr oak NE. 38.65
120 D 10" oak S.S.E. 56.0
1962 Co Hwy Dept 1" pipe
Dec 24" oak SW 84.8 ✓
" cor post S 35.05 ✓
" 8" elm ESE 58.04 ✓
10/17/62 CHD 1/16 corner south of 1/4 1/2 3" x 8" limestone with 2" pipe with stake on top 12" deep; spike & disk in T.P.
RP's spike & disk in T.P. NW 36.0' spike & disk in T.P. NE 62.6'
spike & disk in P.P. SE 52.3'