#540504 (1)

X

1/4 corner 5-8 Hi Forest 105-14.

8-1889 Chas Fraser P434 No 421 S&L. Rurden.
dug extensively for stone owned by Spencer & Rurden
but corner evidently destroyed in building road.

. ran section line set 2 boulders one on top the other.
M & L. 39.77 1/2. 2625.15. and in center of road - found section line - could be center of road East
corner came in center road, 3' north of fence west
- meas south. 39.58 (2612.28'

Co Hwy Dept. B [redacted] 232 Page 3
set Concrete monument, 1' below black top (? Mike W, 1976 over)
limestone monument with Concrete marker on top.

1964 J Kerr E Dedy L S.
United corner drove rod in black top as corner.
Checked county R.P.S 12-1959 replaced limestone with Conc Mon

Disc	power pole	LW	59.6	county 56.47
"	" "	LE	77.2	
"	tele "	NE	96.5	
"	" "	LE	67.85	
Sp	18" oak	LE	50.79	

1964 Meas east 2622.2 R 2625.15
west 2628.0 R 2625.15
Looks like corner could be 3' west
Meas north 1316.86 to 1/16 rod on line.
5271.21 for mile. to N 1/4 S

#540504

Card #2 1/4 5-8 Ht Forest 105-14

1936 Co HD B81 P48+52 inters. of SNE #16 & CAL P (2)

found pointed limestone. 12" dep at line ~~No Mon~~

Sp in oak (18") S 42° E 46.5 Meas North To 1/4 5-32 = 5272.1

NW cor School S 55° E 138.2 (PI = 132+32-3) No angle shown

Sp in FP S 84° W 86.6

HUB - NE 54.1

Meas north 5272.1 = p.32

1959 B232 Co HD limestone, conc marker on top.

Sp D TP NE 96.5 - Sp D PP SW 56.47

Sp D PP SE 77.2

Corner is PI Sta 211+01.62 Δ 0°25' Lt

Meas north 5272.16 JK 1964 5271.2

Meas south 5244.78 R 5245.02 P 434

10-1941 Keir BK 26 P.36 - Stone Mons. with Ties.

8-10-1970 Co surv checked rod by school house tie pinned OK- Meas south to rod Co Meas 5244.78 ahd 5243.6 ahd to fence each 2614.2- then to rod 2629.4. Meas of CIM 2634.8 or 5249.0 for Mile R. 5246.0 or 2612.6 and 2633.4 fence at center & very close. To prop.

4-24-77 Dug at C.H.D. drag tooth. Found drag tooth over 12" concrete monument (4"x4" top and 5"x5" bottom) over a limestone (bottom of limestone up 1' into fill) Old road on clay 5' deep. Dug from drag tooth West 5', North 7', and So. 16'. Found nothing else Removed drag tooth, concrete monument, and limestone. Set 120d at surface of road at drag tooth location. Meas

KP's: CHD Disc on S. side pp # 9951 SW 56.40
CHD Disc N side pp # 9952 SE 77.20
Punch mark top lug W. end CMP in driveway on the So. side of road East ESE 150.32 Not ready For CIM

High forest 1/4 corner 5-8 #540504 13
Gov't Notes Surv by 1853
40.00 Set temp 1/4 sec post
West on true line between Secs 5 & 8
39.92 1/2 Set a 1/4 sec post in mound N 4° E
of earth, coal, charcoal, made
trench, pits, planted Osage Orange
seeds Wits

11-16-82 Set a 1" sq pipe with cap at location of drag tooth formed at road surface. Corner 0 1/2' E. of ℄ C.R. 8 and 4' South of ℄ C.R. 16 and in line fence West.

RPS:
CHD Disc in SE side pp#9951 SW 56.43
CHD Disc in NE side pp#9952 SE 77.23
CS Disc in South side C.P. W 47.97

7-1-96 FOUND 1" SQ PIPE W/CAP IN GOOD CONDITION. SET REF PIPE W/CAP IN NE COR INT CR #16 + CR #8
℄ CR #16 SOUTH 42 1/2' ℄ CR #8 WEST 55'

T@ REF PIPE
3RT P.K. NAIL IN PP# C14-5-15-90 (NEW POLE FOR SERVICE WEST ON WEST SIDE CR 8) TO 1/4 COR 5-8 263° 36' 48"
TO 1/4 COR 5-8 HOR 72.38
7-3-96 REMOVED 1" SQ PIPE W/CAP.
10-25-96 CHD SET 1"SQ PIPE W/CAP.