/ 1981 Yaggy used intersecting 1/4 lines #550109

1/4 Corner Center 1 Rock Dell 105-15

4-1876 Hunter P291 No 286 L1 Knut Larson.

set stake flush with surface at inters lines.

6" Jack Oak west 71 1/2 lks.

set fencing line north & west to bluff line.

line north L 15' W — west L 88°55' E

10-28-78 Visited corner. Found corner post with fences East and South and fence North on the ground. Found a 16" Red Oak with protruding scar on E. side which could possibly be Hunter's brg. tree. Set up the brg. and dist and point came 3 1/2' West and 4 1/2' So of the corner post. We dug from this point to the North side of the fence line but found

nothing. Did not yet dig around corner post.

11/1/78 Center calculated 33' North of t.n. (using Fe @ W¼
Dug from a point 33' North in fence line for
4' West, and 3' South. Found nothing here.
There is a pipe by a State of Mn. sign in the
Fe. North and 48.8 North of the t.n.