/ 7-20-71 set part of steel fence post as corner.
#552309

¼ corner Center 23 Rock Dell 105-15.

9-1878 Hunter P334 No 328 L23 Hans Amundson
E.C. Schon.
set stone 4x10x20 at true transit intersection.

-1/16 west set stake 19.88½ M&L N 89° W.
-1/16 east " " 19.99 " "
-1/16 south " " 20.03½ " N 1¼° E
-1/16 center L W¼ 23 set stake inters lines

8-1963 J Kerr meas line from north at state
water corner - meas 2645 to E-W fence at center.
dug some from center stone - no prober, not conclusive,

7-20-71. Meas from center road at 1/4 23-24. (stone 2.35' east.
1/16 fence south at 1319.65 corrected. R1318.
1/4 line fence north at 2636.95 corrected. iron set to stone found east. R 2636.
Meas from stone at 1/4 22-23 east 2624± R 2624.82.
- set bottom part of steel fence post as corner at meas above little south of corner post of fences E-W-N but lines with main line fences.
- ran direct aerial 28.5 (S) south iron within .2' could be N radios antenna brake so 28.5 south set up within the .2'
No reference to corner. Could not find. 4x10x20 recorded unless some of numerous stones in area were part of stone. No limestones found. Corner accepted—S 1/4 found, N 1/4 assumed. so no N-S 1/4 line run thru heavy crop land, not needed.