#552506


1/4 Corner 25-26 Rock Dell 105-15
Set by Michael Karrick 5-1854
40.00 Set quarter Section post
Black Oak 10 N 75 W 363 = 24.5°
Burr Oak 10 N 48 E 327

10-30-84, 1/4 Cor 25-26: Dug to cover midway between the section corners. Point came in line with new steel fence post fence running West (could find no evidence of an old fence). Line came 2' East of the ℄ N-S road. Dug as follows:



Dug 3' deep to clay.

Found a small stake 1½"x12" lying flat in hard packed black dirt at top of dirt. Could not find hole where it had stood. Scraped to clay. Found another small stake 1¾ x 11" but no hole or mark. Believe both stakes from same piece of wood split down the middle



Both came from ℄ road and midway point area. Probably plowed over in road grading. Searched for bearing trees and had good possibility for NW tree but turned out to be N80°W 240' from point 5' West of ℄ and midway and believe tree a Burr Oak, not a Black Need yet to dig in line with fence from East (1/4 mile East) which better fits 1/16 TS N & S.

4/16/97 settled on corner set M&L for Terry Schwarz survey in E½ SE¼ Sec 25.