X 1-7-72 found limestone and (1" pipe) pipe, no good
#601905 (1)

section corner east 24-25 Dover 106-11
Winona County.

6-1857 John Fraser P 30 No 47 & 24.
used corner to set center and 8 1/16 corners
- 1/16 north & west of above corner
39.90 north to E 1/4 24 then 39.90 (2633.4 N. to E 13-24.

Co Hwy Dept 1943 B 180 P
found 4x8 stone 12" cyp 2' north corner post.
Meas south 5267.1, then ~~Midway~~ 5267.1 to hwy corner
Meas south to old post remains 1' north of fence running east
(over)

2631.4 south of Northeast cor. 25 then
2635.7 south to SE cor 25

1-7-72 Co surv ran and meas from E 13-24 1¼" pipe started 50N 64° W east, line fell 98.5' west of 4"x8" top limestone, down 8"±, which line north of corner post complet. a 1" iron pipe up 2" line south of stone about 1.3'± and lines with fences E and W and line of huge tree south. - Meas 5269.16 K. John Fraser 6-1857 P 30 no 47.

Midway 39.90 2633.4

5-9-72 found 4"x10"x24" limestone at E ¼ 24 4' deep with cross Meas N to above stone 2634.7
then Meas N to E 13-24 2634.46
above ¼ corner .58 E of direct line .12 N of midway

Gov't notes: 1853 N. 80.00 chains Set Post Corner
B.T.'s Blk Oak 14" N 69° W 296 links || Burr Oak 10" N 48° E 332 links
White Oak 8" S 60° W 356 " || Burr Oak 16" S 14° E 611 "

#601905 (2)

Sec Corner East 24-25 Dover Twp - 106-11

6-1984 Tom Ferguson Survey in Sec 30-106-10

6-7-1984 found (4" x 8" Top) stone (down ± 8")
1½ ft North of E-W fence and in line with row of huge Cottonwood Trees running south with the first one South dead and fallen over and lying just east of stone
There is a 1" iron pipe ± 1.3 ft South of the center of the stone (pipe is just about flush with ground or maybe down 2")
Traverse was run S.W'ly and South

60905)

12-14-99
mw RF

E 21-25 106-11 Dover
W 19-30 106-10

Fd 4"X8" Top Stone ± 18" long
1½' North of E-W fence line
3" under ground surface
It falls in line of large
Cottonwood row South end
1.3' North of 1" pipe sticking
2" above ground.
Set Survey marker Sym
& post 1½' South of Stone