8-20-63 set C/M, 5-1965 removed for grading (1)
Culvert centered over corner, little surface covering culvert top
10-10-69 set railroad spike as corner at reference. 1½" down

cert 4-15-75

¼ Corner NO CRIT. N.E. BT. 9-16 Marion 106-13
5-1874 Hunter P243 no 244 L16. Kiefer Bach. Rosenaugh, Hall.
found NEBT and old stake set stone 4 x 8 x 15"
-16 south set stone 2 x 7/14 x 18 M&L. 19.94 (1316.04'
-16 Center NW¼16 set stake M&L 19.98½ on E-W 1/16 line.

4-1875 Hunter P267 no 265 L9. Andrew Pulte
found stone P243. - meas north M&L to temp
stake 20.01¼. 1320.82
-16 east set marked stake 19.95 (1316.7'
-16 center SE¼9 set stake M&L EW 1/16 line 19.94 (1316'

1927 B-3 P38 - Camp K. found corner stone evidently
- Meas west 2655.4 set 1/16 M & L 1327.7.
- ~~Meas north 2631.5 " " " 1315.75~~ (W line SW 1/4 corr)
- Meas North to Cor post 2564? R 2642.?

2-1952. ~~B 57 P36~~ - run line west 2656.35 set 1/16 1328.17.
-16 south grey boulder with notch at 1316.4 M & L.
- Meas west above 1/16 2653.45'

1964 B88 P34 run line east set 1/16 1" pipe M & L 1313.72
set corner south & above 1/16 658.72.
" " " " N 1/4 16 658.0
ran E W 1/16 line NE 1/4 16 set rod M & L 1313.2.
set rod 656.6 east M & L. of 1/16 corner south of N 1/4 16.

#630904 (2)

Card # 2 1/4 9-16 Marion

Orig witness tree in place til road graded it out.
set C/M 8-20-63 removed at 5-65 for grading
Contractor placed culvert so it came exactly center
of corner. set no corner until 10-10-69 then
set railroad spike over culvert, clears culvert.
Zero - little over 1 inch below road surface.

- orig tie - old 16 Din very rotted stump (18" oak) L. 63.52.
- Disc in new 6" Cisco cor post L. 33.8.
- Disc on N side power pole. E 65.03.
- cross in end culv south end. SE 12.48
- " " " " North end. NW 29.49

these crosses on exact Transit line. 74°06' (over AZ 344°06'

set P.K. on line as 1/16 M&L 1327.26 which came 3' south ℄ with ties as follows.

punched cross. east end main curb (8" from end) N,E. 35.0

" " west " " " NNW. 27.92

Top cap Creso post 1' east of ℄ 31.0

SE cor stone column of entrance up 3' N 102.93

B64P63. 1956 Marion Surp- limestone with org B tree 16" br oak. 4' west removed when graded.

16B put on W side 18" br oak SSE 63.52.

set 1/16 west 1/2" rod M&L and 1" pipe 33' ℄. 102.6 to W pillar scout camp entrance - extreme SE cor.

7-10-74 Visited corner + dug up the R.R. spike Left as is.

Govt M-15. Mon. June 1953

59.20 S&I 1/4 S&L Post -- Concrete

Br. Oak 10 N 2 1/2 W 61

" " 8 S 85 W 6