5-27-1965 set C/M over pipe in place 8X10X30 L.S.
#632105 (1)

section corner 20-21-28-29 Marion 166-13

5-1872 Hunter B- 198 no 208 L 28-33 J. Sheldon, F. Andrews.

found boulder set as corner previous survey (unrecorded).

-Meas east 39.78 (2625.48 -chen 2624.16 39.76.

---

corner changed sometime to limestone (8X10X30 glass ck Set A. Armstrong 1941)

5-27-65 found large stone near fence corner of fence North and east, road west of corner due to creek + wet brushy lands. dug big hole moved large stone either east or west. drove pipe and set C/M above. big stone lower than C/M. which did n't stick up (over

Disc corner fence post ~~N 0.97~~ gone

Disc 12" box elder ~~NE 15.4~~ gone

Disc tele pole. ~~SW 15.0~~ gone

punched cross Top of east end 36" road galv. Culvert SSW ~~40.67~~ 40.62

Oct. 1941 A. Armstrong - personal book 3 p. 53
Set Limestone (8"x10"x30") as Set by Meas. of 2640' from South. and proportionate meas. from East and West. Meas. East 2625.4 Then 2624.4
Meas. West 2642.4
Meas. North 2634.3 To Mder. Then. 2634.3 To Sec. Cor.
Ties: Disc. in Tel. p. - N. - 75.3
Disc. in Cor. fe p. - W. 62.4

→ Set survey sign 3' East

7-18-78 Removed broken CIM and set new CIM over 2" iron found below. Stone on E side. Corner 33' E center of rd. and in line with fence E (across creek)
Punched cross E end 36" culvert SSW 40.6 Punched Cross W. end 36" culvert SW 63.83

Section corner 20-21-28-29 Meander 100-25

Govt Mon. Wm Jones 1853 #632105

30.00 S.E. post of corner to section 20-21-28-29
depth of charcoal, + mark mound, brush +
pits, Planted cherry trees S.E. S.W. -
N.E. + N.W.

6-8-89 C.I.M. at surface in ditch & brushy area; monument is near N-S-E fence intersection. retook old ties:

℄ N-S twp. rd. 32.0 W

punch cross E end ~~culvert~~ 36" culvert S.S.W. 40.64

" " W " " " S.W. 63.94

post/sign 3.0 E.
