8-15-69 set C/M over RR spike with org stone and others on all sides - old hydraulic jack on east side.

#632409

1/4 Corner Center 24 Marker 106-13.

6-1901 Robt Fraser P 706 No 620 S 24 John Duly.
Could not find stake in wash claimed set as corner.
set stone at intersection - no mags given.
~~10" brush S 17° E 44 lks (29.04' — 8" brush N 66¾° W 3½ lks 20 79'~~

8-15-1969 J Kerr. found both bearing tree and stone
4 x 18 x 10 in side of wash within 8' of depth of wash.
set railroad spike in bed rock below C/M. with
org stone on west side, flat rock 15" with S South side
and stones of other sides also, corner down about 4"
on steep slope. unbelievable that corner survived

- over.

org bearing tree some 10' above corner on steep slope
L 17° E 29' bark blazed toward corner.
- org bearing tree on level with corner - 20 D in north side up 12" - 20.96' - N 66 3/4° E record O/K.
- 20" brush emerged in wire fenced fence on fence line straight north across wash or gully.
40 D in west side up 18" 17.52'
- corner lies just N W of ancient large corner post accessable from gate of Clark R Gardner farm.
- old hydraulic bumper jack about .45' east of corner up 8"