6-16-69 set C/M over 3/4" x 12" rod. M&L over 1/16 corner south. (#1)
cor 4-15-75
section corner 27-28-33-34 Marion 106-13
#632705
5-1872 Hunter P198 no 208 S28-33 Shelar, Andrews.
Corner gone, set stake from existing witness trees, meas & bearing did not agree so set by measure only.
-16 north set stake 19.83 (1308.8 for line west
-16 south " " 19.94 (1306.04 " " "

6-1876 Hunter P297 No 292 S 34 Brackenridge, Shillwell.
found stake set P198.
-16 south found stake P198 19.96 1/2 M&L. 1317.7.

1930 S Kerr B3 P36. for town board.
found nothing run & meas lines in all for directions.
North to 1/4 27-28 2619.19.
south to S sec cor 33-34 5273.94
- over.

west to 28-29-32-33 - 5274.9.
east to 26-27-34-35 - 5272.6

1932 Co Hwy Dept claims 4X6X18 L.S. actually believed it there - this gone at least 12' fill in place. no attempt to find orig cor.
- County Meas south 2637.8 actual 1969. 2635.9. 1969
" " North 5262.7 to 21-22-27-28.

6-13 and 16-1969 J Kerr did not attempt to find corner in 12' fill. found orig 1/4 33-34 and 1/16 stone north - reset corner as Hunter did M & L. Meas now 1317.95 set C/M over 3/4 X 12" rod
- set 1/2" X 10" rod at 100' on AZ 84°50 in line base PP in yard. this came in Ledge farm drive - 49.5 RP & R Road. NW to pepsi cap RP below.
- pepsi cap on trans line PP# 17567 NE 57°13' AZ 75.41
Corner near east center road south - road in curve north.
-16 south found 4X6X? L.S 27" deep in center road in line fence west.
RP 3/8" X 18" rod just S wire fence west 100' up 3" - Cap center top post west 33.8
- orange cap on trans power pole SW# 17571 173.0'

Section Corner 27-28-33-34 Marion (#2) 106-13

#632705

9-20-76 Retied corner for road grading.
RP's ½" x 2' rod in pasture on line to very top of silo WNW 171.65
½" x 2' rod in pasture on line to NW corner of barn Fdn (near Center 3') SW 218.83
∠ between ½" rods 62° 27' 02"

8-26-1980 See Cor 27-28-33-34: Set a CIM over a 5/8" x 15" iron from RP's taken 9-20-1976. The barn used as a transit tie has been torn down but both irons were in place. We were able to fit the distance to the irons to .01 and the angle between the irons within a few seconds. The line over the NW rod to the silo checked good. The corner is in the ℄ C.R. 111

and 22' North of the center of the driveway ENE
RP: CSD in So. side Pp# 45086 NE 63.92

Geo. Wm. Wm Jones, 1853

50.00 Set a 15"x12"x4" stone at corner to
Sections 27-28-33-34

Book 12 S 45 1/2 E 484 lks
" " 14 S 6 W 527 " "
" " 10 N 3 1/2 W 555 " "