X C.I.M. 1970. #641106 (1)

1/4 corner 10-11 Rock 106-14.
6-1871 Perry P 212 No 220 L 10.
found elm tree BT standing and stump of ash BT.
set oak stake as corner. (Took nest B.T.
9" W. Ash S 41 3/4° E 75 1/2 lks)
- meas west M & L 19.97. (1317'
- meas south M & L 19.90 (1313.4'

1936 A Leonard P 460 B L 10 2/15 H Lillie.
found long limestone with 2"x8" top - 5 1/2' south and
1 1/2' west of twin ash used as corner of fences.
Meas west 2637.7
Meas south 2641.0 Corey

5-1956 McGhee found cut limestone with drill hole on top.

– corner lies 25' west of N-S fence.
6' south of E-W fence.

See 1940 B17-P72.

1940 B103 P61 archie A. O.C.H. found limestone set letter stone with drill hole on top 5X6X22
Meas east 2634.0 to corner in tree. as center 11 on running E-W 1/4 line found 1/2 rod 2' north of line center to E 1/4 2634.9 rod proven. .34' short of recorded Golden Hill plat.

Cat Notes W. B. Yoder 1851

40.00 Set a stone post
White Elm 10 W 2½ W 12 lks
White Ash 8 S 87½ E 25 lks

#641106

Card # 2. 1/4 10-11 Rochester 106-14 (2)

11-13-1970 found limestone 6x8x24. removed stone and set 3/4 x 30" reinf rod. below C.I.M and set stone found on west side of C.I.M. 6" below top of C.I.M. .9 W of C.I.M. - set 3" Channel iron post up 3.5' .7 west of mon. 6' NNE to center between 15" twin elm.

405.7 N 13° W to chiseled cross in top of south concrete curb south apache road on agmich line to center apach water tower stand pipe (not light on top). - this cross 58.1 east of east edge of east catch basin.

11/9/88 FD C.M. IN GOOD CONDITION, SIGN & POST S.W. 1.0' TOOK ADD. RP's 81.4' NW TO SOUTH EDGE OF CENTER CONCRETE SPILLWAY ECONO FOODS PARKING LOT.

CONT. ON OTHER SIDE

1/4 CORNER 10 - 11 ROCH. 106 - 14

11/9/88 CONT. 90.5' NORTH TO SOUTH EDGE OF CENTER CONCRETE SPILLWAY, MOST SOUTH EASTERLY SPILLWAY, FENCES GONE