1 6-25-1964 set C/M over pipe with stone below.
12-14-71. Corner 3/4" pipe W edge Hwy 52. by fence.
3/28/89 DROVE 3.0' LONG FELSPAR PIPE/ c4c OVER #641406 (1)
3/4" PIPE
1/4 corner 14-15 Rochester 106-14.

11-1872. Hunter P210 no 218 S15 d.M. Westfall.
found 1/4 post standing in mound with pits plain.
used only to set Center. not described in survey but
set 1/16 stone west of center and stone replacing stake
set at 1/4 15-16.

4-1901. Sr Fraser P 8 B. Sec 14 and Wside NW 1/4 23.
H Easton.
stake gone but mound and 3 pits
still evident - ran and meas line from 10-11-14-15 over
1/16 corner south set M&L 20.01 (1320.66 and doubled (over

near and drove stake with stone by its side. and found it "brought the corner in mound as found." 1/4 14-15 ①
-16 N found. old stake in stone pile set in former survey.
-16 E found where stake had been pulled out, drove in new stake and found it N & L 19.74 (1302.84
-16 Center S W 1/4 14 found old stake and stump & B.T. reset with new stake and stone.
- Center 14 found iron stake set former survey.

6-25-64. iron pipe over stone long used as corner. set C/M over pipe.
C/M removed for grading of Hwy 52 which will take corner in R/W. set 1" pipe 150' west and another 1" pipe at 250' or another 100' - all on transit line to each other. See card 2.
Spud in fence post W 49.12. Spud in P.P. W N W 32.12

Card # 2. 1/4 14-15 Rochester 106-14. #6414062

1-5-1973. 1/16 corner east between above corner and center 14. seems hard to find. below history of this 1/16 corner.

9-25-1957 JKerr B67 P38 Lenny Schulz survey.
Ran line from 1/4 14-15 to Center 14. on iron pipe set prior to first road re-grade before setting CIM. 10-1963. set 1/16 iron 1/2" rod N 8 E 1303.81 also 1/2" rod as random PoT west on use in road used for direct running of line this PoT near centerroad exactly opposite a pole believed tele pole no identification or measure to pole. No RPs to 1/16 cor. -also believe this rod used as east end transit R.P. when CIM removed at 1/4 14-15 and 2 RP pipes set.

9-7-1959. JKerr. B75 P55 B. Williams private survey. found 1/4 14-15 and 1/16 iron east, staked lot in NW 1/4 & SW 1/4 14.

Cover

set lot corners (1/2" rods with North rods at 33' south of 1/4 line at 216' and 366' west of 1/16 corner and 140' south. (lot size to ℄ road or 1/4 line 150' E-W 173' N-S. ℄ M.H.D. finds 1/16 corner a P.O.T west may reference. again.

12-14-71 drove within 400' ± corner via Bamberwood sub-division, found both RP pipes on N side fence west in good shape also 3/4" pipe now in place as corner, as reset from pipe R.P.s in M.H.D. R/W as drainage complex to protect sheer cut of 60' ± just east - corner area cut at least 5' from area where orig corner cut - found orig spud R Pin bottom area of N side old gate post. 49.12 near due West. other R P gone. left as found.

Rabbitbrush 1/4 corner 14-15 #641406 (3)

Coal Mines on Back

3/28/09 FD 3/4" PIPE SET BY M.H.D., DROVE 3' LONG TELSPAR PIPE/C.I.C. OVER 3/4" PIPE, DROVE SIGN; POST 2.0' WEST, CORNER IS 6' EAST OF R/W FENCE LYING DOWN; 2.0' NORTH OF OLD FENCE RIDGE WEST.

Rp's CSD IN PP SSW 16.83'
CSD IN GUIDE WIRE POST STUB NNW 28.81

Govt Notes W.B. York 1851

$40.00 Set A Section post, in Mound of Earth and Sod deposited charcoal Marked trees and pits planted Osage Orange Set Ed W

12/1875 Thomas Hunter County Surveyor (Pg 284 No. 285)
Found orig. quarter post standing in mound with pits plain. Chained north 20.01½ set ½ with stake then 20.01½ chs to section corner. 1/16th Chained east 19.73½ set 1/16th stake then 19.73½ to center of section set this survey.