#641906 #1

1 10-11-68 set C/M over 12" rod set M & L.

1/4 corner west 1/4 18 Rochester 106-14.

east 1/4 13 Salem 106-15

11-1891 Thos Fraser P461 no 445 S18 J aberwald, etal.

found stone set by Hunter (unrecorded) → Try P.39 and P.50 No 73

1/16 east set stone 4x13x24 with cross on top set on line center 18 - gort record 38.88 actual 39.13 1/4 prop give. 19.00 1/4 then 20.12 3/4 to center 18 stone 3x6x16. with + on top reset from Hunters stone & stake.

Co Hwy Dept 1945 B 159-160. has rail 135.3 east P1 curve - ?

(over)

5-1912 Williams. P 168B L18 A Kutsky.
did not use corner but found stone monuments
at 1/16 east and center sec 18.
- north of above 1/16 to 1/16 on sec line A
- set stone 1311.0 then 1329 to stake set as 1/16 on
sec line which was replaced by stone.

10-1968 J Kerr dug with tractor, roadbed very rocky
and mixed, found vertical wood stake very near M & L
so set C/M M & L 2631.65
- Mc Elvie nail in square redwood corner post NE 54.8
- county disc on SW side power pole # 8041 SE 48.55
- disc on tele pole 374-1 SW 56.9
- disc on black tele pole 374-A-6 NW 56.9
- corner lies slightly south centerline distant county road W
- " " " west " north-south road.

#641806 #2

¼ Corner	West ¼ 18	Rochester	106-14
	East ¼ 13	Salem	106-15

1/16th East 9-22-77 dug 6'x6' on N side of rod set in 1970. Dug through large piece of rock into sand. Found nothing.

W¼ 18 9-28-77 dug on the N side of Kerr CIM. Found 2' of fill on 2' of rock on clay. Did not dig further.

3-1-78 Set a 10" monument over the existing John Kerr CIM

Nov. 1857 T. Hunter Pg. 39 No. 61 shows ¼ Post Meas. East 39.12 chs. to Center Sec 18

March, 1858 T. Hunter Pg. 50 No. 73 shows 1/4 Post.
1/16 East 19.12 chs. then 20 chs. to Center Sec
1/16 North 19.18 chs M&L to Sec Cor.
(See Survey for Incidental & B.L.'s of N.W. 1/4 Sec 18

[illegible]

7/17/89 FD CIM DOWN IN GRAVEL ROAD

7-19-96 CHD TIED OUT CORNER FOR CR 104 GRADING SET 1" Sq PIPE WITH CAP + POST + SIGN 507'± N + 110' E OF CORNER.

TIE @ REF PIPE

XRT TOP CENTER OF SILO W/ WHITE TOP MOST EASTERLY OF 3 SILOS SW TO W 1/4 COR 18 323° 23' 19" HOR 571.92

1/4 CORNER WEST 1/4 18 ROCHESTER 106-14 #3

EAST 1/4 13 SALEM 106-15

#641806

7-19-96 CONT: CHD REMOVED CIM.

(64/1806) F

12-1-98
mw EA

✓W 1/4 18 106-14 Rochester
E 1/4 13 106-15 Salem
Found 3/4" Iron 9" deep in
Crushed rock CR # 104
in good Condition the
Iron falls in ℄ CR # 104
and 10' South of ℄ driveway
@ Mail box # 2520