1 8-25-1970 set 1¼" x 3' pipe W side stone in wash; 1 inch top of pipe centered over stone. ①

#642906

¼ corner 29-30 Rock 106-14

5-1877 Hunter P 314 No 308 S 29 J Dee, B Black & others.

Corner gone, B trees gone, no evidence or knowledge. set marked stake N & L. 39.68½ (2619.2.

-16 east set stake N & L 20.10 3/4 (1327.1'

-16 center N W ¼ set marked stake inters lines.

-16 center S W ¼ set marked stake N & L 19.88 on N-S 1/16 line which proved to be also inters lines.

5-1895 H F Fraser P 572 No 524 S 29 Thos Coleman found stake in plowed area set P 314. Corner proved from many other corners set in that survey one)

– drove stake deep set stone on top of stake or a quote " planted stone & drove new stake as corner".
–16 east found Hayter's stake P314 M & L 20.16½.
drove new stake with stone by side.
– meas north & south. 39.70 (2621.2'
–16 Center of SW¼ 29 drove stake with stone by side
M & L N-S 1/16 line 19.88 – staked this N-S 1/16 line.

8-25 & 26-1970 Co surv found Center 29 limestone and 1/16 corner west, 2 boulders standing vertical and on line with corners east as near as could be seen on 75' ⓢ north – projected line west on this ⓢ one meas of 1325.75 which was direct meas from 1/16 east to Center. dug 8-25-70 random on 75' south and found nothing as this area was in 2' deep wash 8' south of fence running east. on digging on correct meas found 2"x 12" [redacted] limestone egged 16" deep
see card #2.

Card # 2. 1/4 29-30 Rochester 106=14

limestone lay well below bottom of wash indicating by (2)
brown earth that a soil delta had built up from field.
- Corner came at 1326.2 west of 1¼" pipe set as 1/16 with orig
stones at base of pipe down 18" pipe at 1/16 3.2' long #642906
- Corner came 74.52 south of 75' (3) as run - Note 1/16 (3)
corner have been .1' or more less than 75' after finding stones.
- set 3.2' long 1¼" iron pipe as corner on west side of stone
down hill from wash direction with bend so top zeroed over stone.
- RP2 corner lies 7' east of main line of fence running south
~ " " 8' south " " " " " east
- 20 D on S side southerly of 6" granite boulder W NW 3.93 3.87
- west edge of 6" boulder (one of twins) E N E .4
- Coke cap on N side 6" new corner post straight W 9.4
- pepsi cap on W side 6" old cedar post of fence E 4' W A N 8.8 (8.72 corr)

drove 3/8" x 30" reinforcing rod in place of orig 75' ⊛ under fence running north - took direct reference to rod. 74.6' angle of 75' line to corner east to south (corner) 87°24' which computed 3.38 west of corner and 74.52 north at that point it isn't good to set CIM here unless drainage problem solved as this corner so far from occupation lines tried to find human witness, failed so photographed corner 2 ways, close and distant

Gen'l Notes W.B. Verby 1854

4006 Set ⊛ section post.

Bur Oak 12 N 38 W 280 lks

Bur Oak 4 S 37 E 278 lks

10/11/89 FD 1 1/4" PIPE, SET SIGN POST 1.0' NORTH OF CHECKED RPS

20d SPIKE W in W 3.87' (3.93 1970) BOTTLECAP IN C.P. NORTH 8.72' (8.8 1970)

BOTTLECAP IN C.P. W 9.13' (9.4 1970)