T 8-22-70 found limestone set ½" rod on N side on center. 3/4" ?

#642909 D

¼ corner Center 29 Rock 106-14

5-1877 Hunter P 314 no 308 S29 J. Dibble
set stake at true inters line
-16 north set stake M&L 19.86
-16 Center NW¼ set stake inters line
-16 west set stake M&L 20.10 3/4
-16 south set stake M&L 19.91
-16 center SW¼ set stake M&L 19.88 N-S 1/16 line
-16 Center SE¼ set stake inters line.

5-1895 W Fraser P572 no 524 S29 Thos Coleman
found bottom stake set P 314 drove new stake well
down flush with surface.
-16 east deduct find old stake, set new stake stone by side
(1322.31 → M&L 20.03½ Cover

-16 south found stake P 314 found it N&L 19.91 (1314.06
set iron stake with boulder by its side.
-16 center 2W 1/4 set stake with stone by its side (1312.08
N&L 19.88 on N-S 1/16 line
-16 west found stake P 314. found it N&L 20.10 1/2 (1326.93
set pub stake with stone by side.

4-1919 Ch Armstrong P 305 B S28-29. D Blaum.
stone marked on plat.
-16 north iron stake on plat N&L 1318 R 1310.76
2 rod cartway apparently centering on E-W 1/16 line east
thru center of NE 1/4 29.

8-19 & 26-1970 Co surv this corner a key one in re locating the N 1/4 29 for county grading operations. Finally found perfect limestone corner after digging several times from measurements see card # 2.

Card # 2 Center 29 Rochester. #642909 (2)

found 1/16 stone and iron south of center and found S 1/4 29 to be in error. dug & found true limestone set 1895 and found by county in 1939 (see 1/4 29-32), meas S 1/4 29 north 1313.93 R1314.06
- meas 1/16 to center on brush offset east 1312 ± rather short to limestone found 1' SW of corner post. to test corner offset 75' at E 1/4 29 and 1/16 fence west of E 1/4 29 ac't goes east and center stone. brewed this line from 300' east of 1/16 stone west of Center 29 all lined up within inches. so accepted center as true corner. also found W 1/4 29 by this line and meas from center west 1325.75 to 1 1/4" pipe set in place of stones found 2.9' north of old post remains in concrete mfg base in line fence north - meas west to stone found 1326.2 after meas on ⑤ and correcting at ends. 1/16 To center meas on true line

over

1/16 south of center was narrow stone with iron on west side
NW of main corner post - set 3/8" ele fence post bent to zero over stone.
- Meas north to a 5/8" or 3/4" rod shown by Mr Lee from stone at
center 1311.5 but at least 5.3' east of true N-S 1/4 line but in
line of N road fence running east.
- entire meas from stone at center to accepted nail at N 1/4 29
2622.43 R 2621.52 - suggest this iron removed from true line
set up by C Armstrong and set to match fence north (all trees & brush)
ignored corner as it went pertinent to setting N 1/4 corner.
- line from center E along west Sec 1/16 cor 1/4" pipe proved
2325.95 chen 1326.2 line proved W 1/4 29 .48 North of this
line or 1/16 pipe could be moved .24' North to be on line & .27 west
- N-S 1/4 line aerial would place 1/16 south of center as in place as
about .35' west of direct line from 1/2" rod set by stone at center 29
to 1/4 29-32 as reset. 10/11/89 FD 3/4" ROD, POST WITH
CO. SURV. SIGN MISSING 1.0 EAST
FENCES N-S-W