X 9-4-70 set nail rod over axle and stone found
6-30-72 set C/N over axle rod found #650705 (1) 2

1/4 corner west 1/4 7 Salem 106-15 Do County.
east 1/4 12 Canisteo 106-16
10-1884 Hunter P 393 no 384 L 6, 7, 18 X Babcock et al.
Field Book 14 p. 27

Corner gone, but Mr. C Isaacson owns his road fences
west & south were 2 rods out from corner. as this spot
was 39.88 1/4 dist of 2 mile meas and as he owned land
on both sides set stone 2 x 16 x 24 at this point.
2632.96
This 1/4 cor altho on town line lies even more east of
direct line between section corners that does weigh a rod or more.
sec 6

On mutual agreement 10-1884 between Dodge & Olmsted county
surveyors this corner accepted as true corner as others
on the 3.0 mile line to S W 18

(over)

17-1910 Chas Larsen P134B S7 A Holleksen.
found stone with limestone under 2 x 16 x 24 by former survey
- North meas 39.76 (2624.12) to stone with limestone under (found) & to stone with limestone under (found) & or 29.82 to iron rod 2' long on line.
- east 19.16 (1264.56) then 9.99½ (1968.12) to iron rod 1' long.

5-1930 J Kerr B3 P20.
found corner.
- meas east to center (boulder & glass) 2558.5
- 1/16 east set limestone 1306.8 west ¼ center
RP above 1/16 64.0' SE cottonwood - 105' SW cottonwood.
- meas to S line S7 on 1/16 line above. 2637.55'

Conflicting records from stone at W 6-7 To stone at W ¼ 7.
Hunter ¼ total from W-6-7 to W 18-19 or 26320.4 - 39.88 chs 1884
Larsen survey set rod at 6561.04 then 2624.12 To stone deceased
See Card #2

Card #2 W ¼ 7 Salem 106-15 and Mo. County (2)

9-4 To Co Line Meas from C/M at W ¼ 7 down center road
noted fence running east at slightly less than recorded 656.04
#650706
set nail at 2624.0 which came 2' south of road running east.
dug for 12" bolt at 656.04 found it 3' deep - set 1¼ x 3½' pipe
as corner set small 12" bolt at base of pipe as prot. had Marion
and Robert Fowler as witnesses - projected line south carefully
- dug with tractor for W ¼ dug from 2632 (Hunters record)
now and found stone at 2624.65 and 1.76' west of projected
line which would make 1/64th 4' too far east of line left as is
- RP 1/64 Corner .5' south of fence east and 1.0' west centerroad
- ½" wide vertical crack on NE side power pole 39191 NE 56.15
- 40 D diameter on N side 20" brush 6' up, 7' south of fence east 81.7
- stone at W ¼ a hard granite, thin 2 to 4 inches nearly circular
or 16" to 20" with small limestone on top with large wood stake

above stone and 30" piece of buggy axle with round flat and 1" x 1¼" axle shaft on each side stone. set axle deep enough to set C/M on log with large stones on W side - 2 stones on N side small boulder on S side track east of area - will set C/M later
RPs - roots bear cap on SE side power pole 8684 up 5' SW 425
- Coke cap on NE side Power pole 8637 up 5' SE 711.27
- Center lightly blazed 18" Sassafrass NW. 139.2
This bed lies 79.5' ± west & sections north.
Corner lies 2'± south center road east
2'± west center road width south
examined soil south to station 26347 wide & carefully to detect of stone once set at record (2632) and had been removed or worn out. soil clean & undisturbed from top to clean clay. stone had always been where it is.
see Center 7 for 1/16 east
- Meas south to W 7-18. 2637.09
- Meas east to 1/16 stone 1251.5 A & Kerr 1251.7
- Meas east to Center 7 stone 2557.25 A.S Kerr 2558.5

6-30-72 Set C/M

#650706 (3)

¼ Corner West ¼ 7 Salem 106-15

East ¼ 12 Canisteo 106-16 Do Co

Set by John Ball in 1853

40.00 Set post for quarter section corner

Burr Oak 14 N 45° E 109 links

Aspen 10 N 2° W 136 links.