1 10-23-70 set ½" rod as temp corner - orig stone N side road dited.
6-30-72 set 1¼x30" pipe as perm corner. #652609 Temp

¼ corner Center 26 Salem 106-15

6-1887 Hunter P420 No 409. L26 Alice Starkson.
set stone a true enters lines from all ¼ corners.
-1/16 west set stone M&L 19.84½ (1309.8)
-1/16 east set stake M&L 20.00
-1/16 south set stake M&L 19.93 (1315.38)

10-5-70 Co surv. run & meas line from C1M at ¼ 26-27
east. set nail at 1309.0 R1309.77 near exact line fr north
RP 1/16 nail after setting on line Cor PN hard nail 33.1
-center no plate 38599 on slope meas PPNE 116.1
-set nail in center road at 2618 R 261954 used this nail
and C1M as temp E-W ¼ line set 1/16 nail on this line.
RP nail at center - 16D 3rd small elm W of north SW 56.9
16D " " " E " " SE 51.53.

10-23-70 - Meas from PK as ℄E on 26 North. R 2632.08.
found 1/16 fence east at 1316.8±, found random nail set at 2636.
set for E 1/4 26 on random line to be 20.7 N ℄ 2632 from ℄.
- dug first for Center 26, found road eroded away. Dug 10-22-70
before above meas found nothing, on digging 10' south found
2 stone .5" x 3/12" x 16" lying near flat with part of dark spot in
sub clay - decided to dig for E 1/4 26 before final setting.
- after finding E 1/4 26. 26.7 south of random and 2' east ℄ 2636.
re-set Center 26 .27' north and .22' west to be exact line
and proportional distance - west 2617.78 R 2619.54
east 2638.22 R 2640.0 set 1/2" x 2' rod as temp corner.

RP - 20 D on NE side 6" elm SE 45.28
" " NW " " SW 51.08
NW corner glazed tile log house SW 96.0
SE " " " " SSW 84.5

- corner lies near 10' south of road about 1.4 N of Ledge.
6-30-72. set 1"4" x 30" pipe as perm corner. no add. RPS.