8-17-77 CIM

#712604

(1)

1/4 corner 26-35 Quincy 107-11.

10-1896 St Fraser P595 No 541 S23-4-5-6 5 parties

"N" found orig stake located from BT with mark

plain - set stone with stake by side. Leo SW 23

Orig Bdry - 9" B.O. N31°W 204 lks. 1/16 east M&L 1307.62

10-1902 St Fraser P26B S35 Carl Paetzel point 920.22 E 1/4

found stone and stake set P595

1/16 south - set stone 19.95 M&L.

1/16 east set temp stakes 19.81 M&L and 10.91 east 1/4 cor (over

1/16 cor Cents NE 1/4 3S drove iron stake which lies
1 lk N and 16 lks west of NE corner barn.

8-17-77 Found 6x6x16 stone flush with surface with possible stake hole beneath and with drag tooth laying down alongside. Set a CIM over a 1/2 x 2' rod and set the stone on the East side. Corner 3.0 W and 1.5 N of t.n. Corner line with main line of fence East and present fence So but is 3' W of fence N and old fence So. Corner 2' So of large creosote corner post

RP's Spike in W side of pp # 1064 NW 12.81
Spike on SE side wood fence post NE 4.27
Spike on E side 5" cedar NW 56.82

(2)

1/4 CORNER 26-35 QUINCY 107-11 #712604

GOV NOTES 1853 - Wm A JONES

SET 1/4 SECTION CORNER post M&L 39.94 2636 04

9" burr OAK N31W 204 LKS 134 L

MADE TRENCH

STREAM 50 LKS WIDE EAST & DC CRS 532'

CORNER APPARENTLY CORNER OF 4 FARMS

IN rough wooded RAVINE AREA

1/16th So 8-17-77 Found 4½" x 6½" x 14" stone ½' deep 2.3 E of N-S fence and under old fence. Set ½' x 2' rod at stone location and set the stone on the East side

RP CSD E side wood fence post SSW 24.48

6-30-94 Co. Surv. Found CIM with Stone Beside In Good Condition. The Creosote Post North Is Almost Fallen Down.