1/4 Corner S. 1/4 Cor Sec 36 Quincy 107-11
N 1/4 Cor Sec 1 Dover 106 11
#713604

Go.'T notes Sept 1853
Set Post & drove charred stake, built mound with trench.

9-16-77 Dug from t.n. set on ℄ E-W road and in ℄ rd
S. E 2', W 9', N 2', S. 2' by 3½' deep.
Found 5"x 7" black mark with wood pieces in
clean clay. 2' N and 1.35 W of t.n. Mark came
in line with fence N. Set 1" Square by 2'
long iron at surface
RPs CSD NW side pp # 1340 SW 49.23
CSD W side C.P N 57.70
SW corner (concrete) of shed SE 100.55 (slope)

7-18-95 ~ T@ REF PIPE CR9J

4RT P.K. IN PP # 49395 TO S 1/4 36

358° 47' 05"

TO SOUTH 1/4 36

VA 89° 40' 15" dv 00

SLOPE 66.675 HOR 66.675

9-11-97 Set 120d spike in Rock Surface @ Corner location From Ref. pipe

7-15-98

✓ N 1/4 Cor Sec 1 Power 106-11 "713604" C

S 1/4 Cor Sec 36 Grundy 107-11

Drilled hole 0.1' North of ~~fence~~ CSAH #9

In line w/ Twp Rd South

C.S.D. in P.P. NNW 54.00'

C.S.D. in P.P. SSW 89.48'

Most NW Cor Red + White Pole Shed SE 80.27'