1 10-11-1972. set C/M over iron in stake hole. 2 stone on W side C/M #732804 (1)

1/4 corner. 28-33 Haverhill 107-13.

also 1/16 west

4-1859 Hunter P23 No 36 L28. 1/16 east

used corner - set 1/16 north M & L 20 00

5-1876 Hunter caption bottom above page.

set stone at 1/16 corner north.

set corners West ¼ 1/16 ↑ • 5.00 • 15.00 • 3.50 • 5.00 • 11.34 •

" " " ¼ 1/16 28-33 • 5.00 • 15.00 • 3.50 • 5.00 • 11.28 •

meas east to L E 28 39.80

5-1889 Thos Fraser P429 No 417 L28 Col Williams

could find no trace or evidence of corner.

set temp point M & L. 40.10 E/4 = 2647.10' — over —

16 east set stone 2X7X12 1/4 dist on line between section corners. – 20.05 3/8.
–16 north found corner, likely stone set 1876–P23

11– 1892 Thos & W Fraser P499 No 470 S33 Frankland Bros.
found stake set P429.
–16 west set stone M & L no meas. given
–16 east found stone P 429. " " "
–16 south set stone M & L " " "
–16 center NW 1/4 33 set stone M & L N–S 1/16 line.
–16 Center NE 1/4 33 set stake inters lines.

#732804 (2)

Card # 2 1/4 28-33 Haverhill 10-13.
10-13 to 17-1972 set nail at 2647.1 west of stone found at
27-28-33-34 with C/M over stone on line with pipe set
by McGhie 1957 at 28-29-32-33 at recorded distance
1315.4 north of 1/16 stone and on line Kerr stone
set 1927 at 1/4 32-33 proven to be 13.87 too far east
and 5.65 too far north. McGhie used only line S. of 1/16 stone.
10-17 dug and easily found vertical limestone with about
2"x7" top with good sized wood stake still in good condition
on east side of stone. drove rod in stake remains
and set C/M over iron, not stone, left stone as witness.
- meas east final 2647.35 to C/M at NE cor 33.
- set small rod as 1/16 corner east M&L 1323.68 (over

1/16 corner comer 3' S Center road, 7' ± E of N-S fence.

16 West found recorded limestone which had been moved by road pressure but was positive corner, set ½" x 2' rod. adjusting slightly to be exactly N & L 1322.83. x 2 = 2645.66
RP 1/16 41.0 6.5' W & S to 16D on W side new corner post fence S.
69.53 S.E. to nail on N.E. side PP 20226.
corner within 2' ± of N side road - 6' + E of fence S.

RP to C1M 1/4 28-33
33.28 + N W to bottle cap on E side PP # 20221.
69.62 S W to N.E. corner galv sheet covered shed.
29.97 4 W of S to old RP nail on E side PP # 20234.
Corner lies 7' south of direct line.
5' South ℄ E-W road

Shot C1M and corrected RPs in 1979 control Survey.

Cor Wolfs W.B. Verby 1853 EMSL Ramborn Tp 33
40.00 Std A temp Std. post #732804 (3)
West on true line between Sec 4 & 33
40.01½ Std A Std post, in Mound 8° 57' E of Earth
and Soil depositd charcoal mal-trench
and pits planted Osage Orange Stds
N-S at trench
11/1/89 FD CIM DOWN IN GRAVEL RD, IN GOOD
COND.