8-17-1963 set CIM on solid rock. (1)

#740204

1/4 corner 2-11 Cascade 107-14

see file BK3 P57-70

1-1874 Hunt P237 No 239 SW1/2-SE1/4 3 E Cobb to here found stake, badly rotted but standing. witness tree are erroneous having been cut and creased where markings were as surveyors had returned to correct mistake & done prior detailed explanation. small lots survey near SW cor Sec 2.

6-1900 Robt Fraser P646 to 652 No 582 S 1-2-11-12. found no stake but found erroneous witness trees. Hunter claims stake was 2 rods + south & witness tree location. After setting corner (stone) M & L. either 39.44 3/8 or twice 19.94 3/8.

(Farmer said he would set stone)

46 east drove four oak stakes M & L. 19.94 3/8 (1316.3'

RPS. 4" P N 88½W. 22 lks. (1452 10" Jack. S69E 15½ lks (10.23'

(over)

-16 North drone stake M & L 20.03¾ (1322.5'
BP 12" Joak N 53° W 36½ lks (24.1 Red Elm 6" S 47½ W 29½ lks. (18.97

1954 J Kerr B 59 p 145 Lic 2 C. Hanson.
run line SW cor 2 To S¼2. 2631.87 found stone with iron bolt by side set property corners & lines between near road.

1964 J Kerr B 88 P 40 L 2 Ifeo Mitchell.
run line from S¼2 east To ¼16 stone (rough) R 1316.3
total 1315.5 set prop corner for line mark at various points on rock.

8-17-1963 set CIM in place of corner stone on hard rock base.
corner lies just east of N-S-W fences. on hilltop
above Ted Mitchell building site.
- nails sub. 18" Maple & NNE 45.3.
" " 10" Cedar oak S 72.8 (Pd) stake & B.T. center SW¼2

4-1913 D Williams. P 200 B. ¼16 W iron stake - ¼16 North limestone with + set

Cascade 1/4 corner 2-11 #7402204 (2)
Cow's Woods Mr. Hancock 1854
40.00 Set stamp 1/4 stake post
West on true line between sec 2-11
40.00 Set 1/4 sec post V 6 "13"
White Oak 10 S 13 W's.
Jack Oak 10 N 25 W 60

6-1900 R. Fraser - Field Bk 15 p. 3-20
At 'B' - 1/4 Cor 2-11 - Set stake marked 1/4 S. and Mr. Blanchard said he would put in Stone
Took wit. Trees N 78°E 19 lks D.O. 6"
S 11°E 17 lks D.O. 5"
N 58°W 15½ lks Basswood 8"
at 1/16 Cor-West. set stake marked and Took wit. Trees
S 3½°E 19½ lks D.O. 6" — N30½ W 17 lks D.O. 4"
Cover

R.F. 1900 survey Cont'. at Cen. S.W.1/4 Sec. 2 set stake marked and stone Took wit. Trees S 13°W 31 lks 20.46'
Pin 0. 12" & N88½°W Red Elm 8" 16 lks. = 10.56'

March 1856 Thos. Hunter shows 1/4 Post (Pg. 1 No. 1)
1/16 west 20.02 chs. M & L Bearing Tree to 1/16 Cor.
N 70 1/4° E 147 links

1/16 North 20.34 Chs. M & L

6-11-1980 (1980 Romon. BK) 1/16 North: Found 1¼" pipe up 1' East of the base of old corner post to fences N-S-W. There was a 2"x 4" topped shattered limestone sticking 4" out of the ground .5 South and .35 West of the pipe.
(SEE 1913 D. Williams)