/ 6-1-72 set CIM over 5/8"x12" iron #7406069 (1)
mag stone found on S. side
4-3-1975 set short CIM over CIM - up To Blacktop Surface
1/4 Corner west 1/4 6 Cascade 107-14
east 1/4 1 Kalmar 107-15
6-1873 Hunter P232 No 234 & 1 N Bowman, W Grunion
found stone in center road undisputed.
1313.4.
-1/16 west set stone 2x7x24 M&L 19.90 N 89° 38 W.
-1/16 south set stone 4x 4/12 x 19 M&L 19.97½ N ¼° W
1318.35
-1/16 center S E 1/4 sec 1 set stone 2x8x20 intersection lines.

6-1874 Hunter P229 No 232 & 6 M. Colby.
found stone boulder in center road.

(over)

6-1870 Perry P122 no 157 & 12 C Grasley.
found stone as east 1/4 section 1 during survey

present day terrain, chance good, good fence east & west
fairly level, no serious slopes near corner.

12-3-71. Bearings. Meas from nail at W 6-7 E 1-12.
found 1/16 fence east at 1313.5 R 1318.35.
found 1/4 fence west at 2631.6 R 2636.7
M. 1318.1 from 1/16 fence east to 1/4 fence W. R 1318.1
believe this nail close as meas to W 1/4 7. 5271.6 R 5273.4

See Card # 2.

Card # 2. W 1/4 6 Cascade 107-14 E 1/4 1 Kalmar 107-15
#740606 (2)

6-1-72. Co surv. found nail set 12-71 at 2631.6 north
1.00 nail in intersection at W 6-7 (which could go 3.6 S.
- Meas W from .00 nail to 1/16 fence S near 1320' - finally found
1/16 stone 2' deep sign as recorded 2"x7" top. set odd shaped
5" x 16" x 12" boulder on top. (1/16 West).
- 1/16. 3.0' E fence S - 3' SW to Center Corner P. 2'+ S to fence.
figured 1/16 stone at 1317+ from .00 so dug west and
found broken L.S. 4"x7"x15" bottom half vertical + position
- stone came. 1.05' N and 3.9' W of .00 nail (W 1/4 6).
- stone 2'+ N of post on fence E not as much N of fence W.
bvp

- set 5/8" x 12"+ rod in place of stone with C I M above rod with orig stone pieces on S side base of C I M.

46.57 W to hand hole in 1½" bent on North side of trans line PP up 4' # 24329.

104.6 S 2° W to spiral Cap on E side PP 23993.

- Meas W to 1/16. Will Zap.
- Meas S 2631.6 + 4.0 + 1.05 = 2636.65± should Zap.

4-3-75 Dug in blacktop road and set a 10" C.I.M. over previous one set in 1972. Took no additional R.P.'s

Geol Notes.

40.00 Soil [illegible], + stone [illegible] to [illegible] soil. [illegible]. Soil [illegible], + clay [illegible]. S.E. Ledge [illegible], N.E. [illegible] stone.

1/4 CORNER WEST 1/4 6 CASCADE 107-14 (3)
EAST 1/4 1 KALMAR 107-15 #7406016

8-31-95 - FOUND CIM IN GOOD CONDITION 4' WEST OF ℄ TRAVELED ROAD. REFERENCED FOR ROAD GRADING PROJECT.
T@ W1/4 6 SET 1"SQ PIPE W/CAP ON LINE TO P.K. IN PP #24330
TO REF PIPE
VA 93° 40' 20"
SLOPE 74.69 [redacted] HOR 74.55

8-12-97 - SET 120d SPIKE FROM REF PIPE. CORNER FALLS IN ℄ N-S TWP ROAD. IN LINE OF PP LINE RUNNING WEST.