1 4-7-75 Set a C.I.M. over a 5/8"x14" iron rod on line - mens. from North. #740705 (1)

section corner west 7-18 Cascade 107-14.
east 12-13 Kalmar 107-15

6-1870 Perry P122 no 157 S12 C Grassley.
found stone monument undisputed.

—1/16 north set stone 4x5x22 M&L 19.97½ 1318.35
—1/16 west set stone 5½x5½x17 & stake M&L 19.99 1319.34 line.
—1/16 center SE¼ 12. set stone 5x5x15 M&L 19.98½ N-S 1/16 1319.01.

11-1890 Thos Fraser. P445 no 430 S18-19 Yoman, Crawford.
corner comes in 4' road cut likely gone. (poor survey)
set nothing - on township line

See loose leaf page by T. Fraser 1890
Copy of R.J. Perry Survey of Sec. 18 - July 1871

(OVER)

present day terrain - looks fair to good as far as road fill - evidently road raised again - doubtful.

12-3-71. Co surv - set nail in center crossroads road west being abandoned for years now farm field road.
RP nail 60.96 SE to brg punch hole on SW side PP level # 24073.
46.26 SW. To brg punch hole on SE side lone tele pole no wire
- mens north - set nail at 1300 (no fences E & W).
RP nail. 35.45 ESE to nail S side PP.
75.25 NNW to N edge tele warning sign post R2636.7
- 2635.6 to nail set at W¼ T. on line 8 mens from east.
RP nail. 71.61 SE To orang cap on SW side PP. 24056.
46.01 SW To root beer cap on SE side. tele pole.
- used nail as 00. cont north.
set nail at. 1317.0 in line fence west. R. 1318.35
RP 52.18 SE to ground wire on N side power pole. W.
34.35 SW. To center brg 2" pipe brg cor post. high as post brg Cor 2

Card # 2. W 7-18 Cascade 107-14. #740705 (12)
E 12-13 Kalmar 107-15.
12-3-71 Cont. line north to rail at an W 6-7 E 1-12.
Meas 2640 indicating something long. R 26 36.7

Meas from rail at W 9-18 E 12-13 west
set 120 D at 1320. on N side road on line corner post
at 1/4 12-13 Kalmar now behind 25' N & true corner.
RP 120 D. 20.2 S to flag on fence which is on line over rail
to flag on wire on fence north side of road.
- set 120 D at 2638 4' E of corner post. R 2638.68.
- Meas north of 120 D found recorded 4 X 5½ X 18 L stone
set as 1/16 corner by Perry 1870 at 12945 R. 1319.34
6-6-72 found 1/16 stone west. 26± E of 120 D set at 1320.
stone leaning westerly but base of stone print plainly visible (over)

6-6-72 dug enormous hole. to clear clay. found nothing
only that Chas Fraser was right that corner was gone.
ac 1/16 stones both N & S of W 1/4 7 found. can replace corner
easily. believe 1/16 W. not midway to N-S 1/4 line Sec 12. Kalmar
See W 1/4 7 for details of 1/16 corners ✓
—16 W. stone 5½ x 5½ x 17 leaning west but definate
base of stone in soil with stone chip from side of stone
in place - replaced stone. set ½" x 16" pipe riser.
177' W SW to punched brass in S end 5" old road culv.
49.3 SW to center large 26"± ash type tree
43.0 SE to center large 24"± burr oak tree
will zap more later.

(3)

West 7-18 Cascade 107-14 #740705

East 12-13 Kalmar 107-15

4-7-75

Set a C.I.M. over a 5/8" x 14" rod on line from the North ¼ double the distance from the 1/16 North, making each ¼ mi. N. = to 1318.03.

Corner falls in "T" intersection 2.3 East of N-S ℄ + 2.6' North of ℄ E.

R.P.'s

C. S disc on N.E. side P.P.# 24073 S.E. 58.37

C. S. disc on N.W. side Cor. post N.E. 63.43

C. S disc on S.W. side cut off P. Pole cor. post N.W. 48.6'

Give Notice,

80.00 Set post & drive channel anchor same to archives 7-12-13-18. Built mound & trench.

Planted S.E. Osage Orange N.E. Apple seeds.

11/20/89 FD CIM IN GOOD COND.