X 4-1954 set full length buggy axle over orig stone (1)
3-1973 corner now 3/4" capped pipe near. #741104
1/4 corner NOTE: See Unfinished cert file 11-14 Cascade. 107-14
2-1878 Hunter P329 No 323 S14 R Elliot and others
corner gone See Field BK5 P40 searched and dug extensively. SEB tree standing
Govt notes call for S 67° E 2.45 chs. - bearing wrong as it would
bring corner 6 rods too far south of where Md Philo Boardman said
stake stood only a few years before. - Measured section line E
set stone 3 x 8 x 20 Midway 1/4 So. of line and 2.45 chs from B tree S 30° E which
brought corner where it should be and in line of blazes west.
-16 west set marked stake M&L 19.98 took 2 witness trees.
-16 south set stone 4 x 10 x 20 with stake on east side This 1/16 stone fd
M&L 19.96. 1317.36 4" brook. N 84° W 24 lks. by RF 1900 - took B.T.s N62°W 25 lks 30 in. dia. S65°W 30 in. dia.

1-1900 R Fraser. P646 to 652 No 582. S1-2-11-12.
2637.36
did not find corner - set temp point 39.96 from S E cor 11.

-16 east stone (set by R Fraser on caption) M & L 19.98
-16 north " " " " " " 19.84 records very faint
see below.

4-1954 J Kerr B 59 P 16 NE 1/4 14 C Boldman.
found limestone over 5' deep set full length buggy axle as
riser corner. - meas east to 1/4 cor. 2635.35.
set points at 658.87 and 1317.75.
- south set 1 1/4" pipe at 539.0 and 1/16 corner at 1314.12.
Spike in 12" oak. N 38.85 - ~~Spike in 12" oak~~ gone 3-73. NE 40.05
Southwest corner house foundation NNE 84.7

1959 J Kerr. B 94 P 26. K Nelson sub layout.
1/16 south 3/4" pipe in line fence east 41.5' west of ℄ road.
with prop corner rod under fence east likely 33' ± to ℄.
265' east to pipe from likely ℄.

4-1900 R Fraser P 665 no 591. ℄ 14 Richardson Birch
dug 3 tons meas N line 14 brush & trees finally found stone. Cornerstone
N 33 1/4 E 129 L. 85.14

Card # 2. 1/4 11-14. Cascade. 10 7-14. #741104 (2)

3-26-1973 found Center 14 stone and 1" reinf rod on each side. ran Traverse north to 1/16 pipe set by J Kerr 4-1954 B59 P 16. M & L. 1314.12. Now —
also meas to 1 3/4" pipe up 12" on south bank of river set at 539' south of buggy axle set over 1/4 11-14 stone in above survey. Completed Traverse from. area just east of 1/4 11-14 ~~asfound~~ which is now 3/4" or 1/2" pipe with McKhie survey cap. Numerous nails in trees set by McKhie
Meas now as follows ~~compiled~~ from Traverse south —
Meas S to J Kerr pipe set at 539.0 539.12 found on line.
1/16 pipe set J Kerr 1952. 1314.3 S 1314.38 R.
or .08 east .04 south of M & L 1314.34 John 1314.12.
1878 Hunter 1317.36
(over)

3-27-73. dug deep and found recorded limestone at 1/16. between center 1/4. and 1/4 11-14. about 3' deep stone about .4 east and .9 south of J Kerr pipe. as J Kerr pipe came so close to M&L. did not move. pipe would likely use stone if line was ran west to stone if found recorded as. Center NW 1/4 14 set by hunter

3-28-73. dug entire area near J Kerr 1/16 rod found south of center 14 for early survey stake found nothing. as Hunters stake set in early February 1878.
John Kerr rod now 1.35 west of line at 1315.84 from C 14.
did not reset. this 1/16. left J Kerr rod as found.
- P.O.T. (1/2" rod on dike on line 1277.24 N. 1362.28 S
Total mile N-S 1/4 line 2639.52 S 1/2 - 2628.68 N 1/2.

Gate Notes
40.00 Dr. 1/4 [illegible]
Brook 12 S 67 E 2.45
" 8 N 65 W 1.15

#741104 (3)

1/4 Corner 11-14, Cascade:

4-27-83, 1/4 Cor 11-14: Found Ken McGhee pipe and cap. Removed and dug down to Kerr buggy axle 2' deep. Set CIM over axle. Pipe was set over axle. Corner on berm on SW 1/4 side of driveway on curve from East to NW bent in line with the center of the road further East. Corner appx 85' SW of SW corner of house foundation. Set a survey marker sign and post 1.15 South and a plastic fence post .5 West

LP: Old spike in West side of 14" Burr Oak N 1/4 38.85
Old spike in East side of 14" Burr Oak NE 26.19