X

#741109 (1)

1/4 Corner Center 11 Cascade 107-14.

6-1900 R Fraser P646 to 652. No 582. S 1-2-11-12
See field BK 15 P. 3-30
Corner run in by Hunter. Pioneer claim & came near certain stump. some trees blazed NOTE See BK 15 P. 8-9
ran intera lines from all 1/4 corners. R.F. could not find F.H. S.1/4 Cor. 11
within 2 feet of stump. drove burr oak stake and set stone 30" x 18" x 2"
N 5 Links Jack Oak - S 9° W. Jack oak. 23 1/2 links.
16-south stone set (capture) M & L 19.89 = 1312.74
-16 north corner set. M & L 19.75 3/4
-64 north " " " 9.87 1/8
extensive work & witness trees (notes hard to read.

11-1939 J Kerr B 16 P 60 Boardman school.
found stone at Center on running stadia line 2641
from W 1/4 11 found stone and iron pipe at W 1/4 11.
drove 1/2" steel staff with gear on west side of stone at Center.
-RPs Oak tree N 3.3'
16" " E 30.0'

---

8-1975 Mc+B. Sec. 11 Plat for Buckthorn Sub.
Established Co-ord. of Cen. 11 by Computation which
brings Center at 4.67 East and 1.61 So. of Stone
which was inplace. Nothing set at this time.
also 1/16 Cor. stone North found to be incorrect.
Correct 1/16 Cor. should go.- 0.88' N. & 4.30' East of
stone inplace. See Traverse Sheet No. 3-59

#741109 (2)

1/4 CORNER CENTER 11 CASCADE 107-14

4/4/90 FD STONE WITH FLAT IRON BESIDE ALSO PIPE/CAP #6507 ± 4 1/2' EASTERLY OF STONE WITH FIBERGLASS POST BESIDE PIPE.