#942509

8-30-61 set C/M in place of stone (1)

1/4 corner Center 25 Cascade 107-14.

limestone with cross in place. not on true line?
set C/M.

Center 14" burr oak 8' north of fence. NW 17.5
Center 7" white oak SE 29.9

B 1863 BK. A p.69 P.C. Compton set Center 25 at intersecting 1/4 lines. Brg. tree given but should check at courthouse!

over

May, 1856 Thos Hunter Pg. 8 No 13 Shows Center Sec,
1/16 west 20.71 chs. m & L to 1/4 Post.
1/16 south 19.73 chs. m & L to 1/4 Post
Center of S. W 1/4 meas. west 20.28 & 19.66 chs. North.
To Describe N.W 1/4 of S.W. 1/4 Sec. 25

---

Sept, 1858 T. Hunter Pg. 56 No. 82 Shows Center Sec.
meas. west 41.42 chs. to 1/4 Post.
1/16 East 19.67 chs. m & L to 1/4 Post
1/16 North 19.97 chs.
(See Survey for breakdown in N 1/2 sec. 25

---

July, 1859 T. Hunter Pg. 62 No. 88 Shows Cen Sec.
1/16 South 19.73 chs. m & L to 1/4 Post.

#742509 (2)

1/4 CORNER CENTER 25 CASCADE 107-14
FD CIM WITH TOP SECTIONS BROKEN OFF,
BUT BOTTOM SEEMS GOOD, THIS FALLS ON LINE
BETWEEN NORTHERN HEIGHTS 4th ADD LOTS 5 & 6 AND
PECK'S HILLS 2ND SUB 84' WEST OF E
19th ST N.E. ON CURVE. RP'S

NW COR. HOUSE #826 S.S.W 29.51
SE COR. CONC. HOUSE #820 WALKWAY N 39.59
THE CIM IS 1/2 SOUTH OF E-W CHAIN LINK FENCE
6 TRUNKED BUR OAK USED BY J. KERR (1961)
N.W. 17.5'