#743205

10-19-1963 set C/M in place of over orig stone (1)

section corner south 31-32 Cascade 107-14.
North 5-6 Rock 106-14
3-1902 2t Fraser P36B L6 A Rose.
found stone corner - used only to set N¼6
easting & westing.

12-1921 J Kerr P374B L31 Sisters St Francis
found stake & stone with B trees -
18" oak NE 103.4'
15" tree NW 70.5'

(over)

Corner used numerous surveys, in open hillside pasture

10-1963 JKer found stone with help from
Mr Nigon and his sons.
set C/M over or beside dog stone (C/M corner).
- heavy oak post with hub nailed on d 2.1.
- Sp 15" hickory (June 24, 1974 Tree now 20" or better) North 70.5
- Sp 24" Oak ENE 103.4
Corner lies in open pasture hillside in line center
conc highway east of Nigon buildings about ⅓ way up
hill west 6 or 8 hundred feet
Cor hard to locate without Tree Tres. (June 24, 1974)
W. edge of 43" dia. Tile-spring outlet - E-NE 38.2 } 4-2 1982
(1982) 48" willow Tree - East — 79'

Sec. Corner South 31-32 Cascade 107-14 Card # (2)
North 5-6 Rochester 106-14 #743205

Gov't Notes: Set post for Corner

Black oak 8"	N 88° W	64 lks.
Black oak 8"	N 30° E	24 lks.
Black oak 5"	S 15° W	24 lks.
Black oak 7"	S 38° E	48 lks.

11-1856 T. Hunter P 19 No. 31 S.W. ¼ 32, & N.W. ¼ Sec 5, 106-14 & N.E. ¼ Sec. 6, 106-14

1/16 East 19.71 M & L

1/16 South 19.73 Then 20.00 to ¼ Cor 5-6 Rochester

1/16 North 1968½ M & L - B.T.'s (N 70½° W 72½ lks.)(S 35° E 57 lks.)

4-2-1982 Co. Surv. fd CIM flush with ground
Took extra Ties as shown on Card #1

8/30/89 FD CIM WITH BROKEN TOP

SET SIGN

¼ POST 1.0' WEST

1939 CHD stone with ¾" rod on top

RPs Spk on top of fence post NE 38.7'
Spk on top of fence post NW 55.3'
two south & north 66'