#750404 (1)

X

1/4 corner 4-9 Kalmar 10 7-15.

10-1910 Chas Larson P136 B S4. Helen Gage.
found wood stake as 1/4 corner.
-1/16 west set gaspipe M&L. 19.80 chs. with
gaspipe set 10.19 north of above 1/16 cor.

1947 Starr B32 P62. S4.
found or set stone ran line north to area center 4.
set 1/16 at 1312.0. for line west also point midway.
1/16 cor and center section 4. for prop line west.

(over)

11-1960 J Kerr B 80 P 57 Rundell.
North 1/4 9 a stone at edge cattle path. drove 5/8" or reamer rode 3 to 4' long on 2 sides of stone to save it.
– Meas south ~~2621.3~~? with rod in center road at 646' ~~south~~ North of center 9.
Corner lies not far north of fence corner S & W.

1-1878 Hunter (P326 No320) reset a stake from Bearing tree and stumps of bearing tree
Meas East 40.11 / Mean N = 2603.84
Mean E = 2633.063 to CIM
10-28-75 Found 4" square topped limestone up 3" with rod on E side and rod with nut on N side as recorded by J.K. Corner is in line of fence W and 4' NW of tree as corner post to fences S and W.

1/4 Corner 4-9 Kalmar 107-15

#750404

10-28-75 Found 3"x5"x?" limestone with cross on top 1½' S. of corner post. Stone referred to by Chas. Larsen as not M&L. We found it 1.11' out of line and meas. N = 1291.02
meas E = 1312.66
Looked for C.L.'s cpw pipe but M&L fall in deep cut road to field. Found nothing.

Gov't Notes Kanick '854

40.00 set temp 1/4 cor'd post
West on true line between set. 1/4 & 1/4 20'
40.00 set 1/4 cor'd post
Sugar 10 N 15 W 89
" " 5 50 E 48

(1856) T.H over

Dec, 1856 Thos. Hunter Pg. No. 32 Shows 1/4 Post
1/16 west 19.84 chs. M&L - B.T.'s (N 77½° E 33 lks.) (N 66¾° W 13 lks.)
1/16 North 20.07 chs. M&L stands in the River
B.T. (Elm N 11¾° E 92 lks.)