Nov. 1975 — Checked fence post used as Center Section
found post Taken E-W ¼ line but ±4' Too far East
(See Sheet in File)

¼ corner Center 4 Kalmar 107-15. ①

#750409

~~no records~~ -

1947- J Kerr B 32 P62. Kalmar town Board SW¼4.
Run line S ¼ 4 north .2624' used some kind of
point as center
elaborate survey in SW ¼ 4.

3-22-1892 T Fraser. P474 S479 S Allen, E Secr.
found center stake standing and marked SE B T. standing
taken by Perry. S 44° E 8½2 (5.61' 10" red elm.
New B tree → Backword S 21½ E 14L 9.24'
run line meet set stakes at 7½ chs. (495' and 12½ chs (825'

Dec, 1856 Thos. Hunter Pg. 20 No. 32 Show Center Section
with 3 B.T.'s (N 63° W 28 lks.)(S 75° W 28 lks.)(S 21½° E 14 lks.)
1/16 West 20 chs. M&L - B.T.'s (N 33° E 40 lks.)(N 15° W 53 lks.)
1/64 South 10.03½ chs M&L - B.T.'s (N 23½° W 32 lks.)(S 22° W 8 lks.)
1/16 South 20.07 chs M&L Stands in the River
B.T.'s (Elm N 11 3/4° E 92 lks.)
Section is Broken in 1/4's of 1/4's of 1/4's with
Bearing Trees to all Corners used.

Note: 1/16 West stands in the River and a stake stands
on the Bank 50 links North of the 1/16 Sec. Post.

Pg. 82 No. 124 H.E. Horton Shows Center Sec. used
to Survey S0½ N.E. 1/4 & N0 1/2 S.E. 1/4 Sec. 4
1/16 East 19.80 chs. M&L to 1/4 Cor. 3-4

1/4 Corner Center 4 Kalmar 107-15 (2)
#750407
Feb, 1867 H.E. Horton Pg. 81 No. 122 subdivision
of N.E. 1/4 of N.W 1/4 sec 4 (See survey for B.T.'s).