X 3-12-81 Reset 3/4" rod & cap from reference #752909 (1)

3/4" iron rod set Sept. 1974 by McGhie & Betts at inter. lines

1/4 corner Center 29. Kalmar 107-15

5-1871 Perry P162 No 185 L 29-30-31-32

located temp point at inters lines.

10-1939 J Kerr. B84 P72 Co H D 9-23-36

Bk 16 P.40 and B520 - did not set Center of Sec. 29

(?set) limestone 2 x 6 x 12. which came .9' west of N 1/4 line

Power pole NE 41.4 Meas south 2638.0

fence post NW 52.5 Meas north 2633.3

9-1936 Co H D found 2x6x12 L stone .9' west of true

N-S 1/4 line - N - 2633.3 - S 2638.0

Sta 2638.0 corner on line road. P.O.T. 2683.6 Topo over

Center line road west 2638.0

Dug in 1974 For Corner but found Nothing.
Center should be at intersecting Lines as
set by McGhie + Betts

1977 BK. 406 pg 2 } same set 11-5-80

3/4" rod in place set by McGhie + Betts
R.R. by C.H. Dept.

Spike + disc P.P. N-W 11405
" in P.P. N.E. 3930

5-13-1980 (1980 Remon. BK. P. 32) Center 29 : Took RP's to rod before grading
- Punch hole top West end Concrete culvert (most N'ly of pair) SW 73.74
- Punch hole top East end Concrete culvert (most N'ly of pair) SE 62.42
- Chiseled "L" in NE'ly portion of ring to manhole cover in catch basin SW 73.42
- Chisled "L" in NW'ly portion of ring to manhole cover in catch basin SE 65.02

#752909 (2)

1/4 Corner Center 29 Kalmar 107-15

3-12-81 (1981 remon blk) Reset a 5/8" iron rod and cap from the reference.

11-7-82, Center 29: Set a short piece of 1" sq pipe / cap in new concrete of C.R. 5 at the intersection of the 1/4 line by steel Corner .36 West of ℄ crack C.R. 5 and in ℄ Crushed rock road West. The corner is .09 West and .08 South of the point noted here from references taken 5-13-80. (Could have gone .02 further West but couldn't get it any closer). We decided to retrace the section because the point set up from 1980 RPs came .11 E. of the N-S 1/4 line and we have deceived that the CIM @ the W 1/4 Cr 29 was badly tilted and probably was when previous measurements were taken.

RPS } Chiseled "7" in ring of manhole SE 64.97
RPS } Chiseled "7" in ring of manhole SW 73.32

CENTER 29 107-15 KALMAR 8-6-98 EPA BB

(752909)D FOUND 1" SQ PIPE/CAP AT SURFACE IN

℄ OF CR #9.