1/4 Corner N. 1/4 Sec. 6 Quincy 107-11
8/14/80 Set Cmt S 1/4 31-108-11 #813104

Gov't Notes. Sept 1853
Set Post for 1/4 Sec Cor - dug Trench
Burr Oak 12" S 12½° W 254 links
161.64'

11-16-1979 Dug here in line with the fence South. Found a greenish three-sided boulder (5"/7"/8" x 16" long) coming to a point standing 1½' deep with base in clay. Drove a ⅝" x 23" rod where the stone stood and set the stone on the West side. The corner is 2' North & and in line with the fence So.

LKP 2 W 6.77 N 8.25

11-19-1979 We dug here from a point 12' East and 8' South of the DNR traverse point South 12', West 4', and East 3'. We were digging here to cover Kent measure from NW6

and also the prorated Gait measure from NW 6 to NE 4
We did not find anything.

1/16th West 11/19/79 We started digging in line with the fence South and on line from NW 6 to the stone found at N¼6. The area had been cut to clay in road construction - clay being just 8" beneath the road surface so did not dig further

8-14-80 Set CIM over iron set in 1979 in stone location
The corner is 6½ East of fence North and 2' North of ℄ E-W road and 1' West of fence South.
RP's: CSD in corner post NNW 39.18
CSD in pp # 43493 SE 39.22
CSD in pp # 32981 NE 125.51